

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL041031	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 10/28/2016
NAME OF PROVIDER OR SUPPLIER BROOKDALE NORTHWEST GREENSBORO		STREET ADDRESS, CITY, STATE, ZIP CODE 5809 OLD OAK RIDGE ROAD GREENSBORO, NC 27410		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
(C 000)	Initial Comments Report of a Follow Up Survey by Billy S. Bryant conducted on 10/28/2016. Deficiencies noted during the Biennial Survey on 09/07/2016 remain to be corrected.	(C 000)		
(C 189)	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 2- Based on observation, the facility has not maintained in a safe condition penetrations in the one-hour roof/ceiling assembly. This could affect all residents and staff if fire were not contained in the room/space of origin. Finding on 10/28/2016: (a) The attic access panel has holes in it's construction at the opening edges located outside Room 19. 3- Based on observation there is a failure to maintain the facility's fire safety systems in a safe manner as evidenced by gaps and open penetrations in the fire resistant rated ceilings. Fire resistant rated ceilings must be free of gaps and openings in order to resist the spread of fire and smoke in the event of a fire. Penetrations or	(C 189)	New Attic access door installed 11-14-2016	

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

STATE FORM

6899

2M4022

If continuation sheet 1 of 2

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL041031	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED R 10/28/2016
NAME OF PROVIDER OR SUPPLIER BROOKDALE NORTHWEST GREENSBORO		STREET ADDRESS, CITY, STATE, ZIP CODE 5809 OLD OAK RIDGE ROAD GREENSBORO, NC 27410		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
(C 189)	Continued From page 1 holes in fire resistant rated ceilings could effect the occupants of the facility by allowing fire and smoke to spread beyond the area of origin. Findings on 10/28/2016: (a) Due to a new installation, there are two 2" EMT ceiling penetrations in Mech Room B that are not sealed with a fire resistant sealant.	(C 189)	EMT ceiling penetrations Sealed with fire resistant sealant 10-31-2016	