

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL092161	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 05/16/2018
NAME OF PROVIDER OR SUPPLIER WALTONWOOD CARY PARKWAY		STREET ADDRESS, CITY, STATE, ZIP CODE 750 SE CARY PARKWAY CARY, NC 27511		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Construction Section Biennial Survey report by Frank Strickland and Suzanna Fay on May 16, 2018: This facility was first licensed on 07/13/2010 and is currently licensed for 85 Beds with a 33 Bed Special Care Unit. Therefore, this facility was surveyed for conformance with the applicable portions of the 2009 Edition of the North Carolina Building Code(s), Institutional Occupancy and the 2005 Rules for Licensing of Adult Care Homes of Seven or More Beds in effect at the time of initial licensure. Deficiencies have been cited and a Plan of Correction is required.	C 000		
C 101	Existing Licensed Fac- No less than '71 Rules SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0301 APPLICATION OF PHYSICAL PLANT REQUIREMENTS The physical plant requirements for each adult care home shall be applied as follows: (2) Except where otherwise specified, existing licensed facilities or portions of existing licensed facilities shall meet licensure and code requirements in effect at the time of construction, change in service or bed count, addition, renovation, or alteration; however in no case shall the requirements for any licensed facility where no addition or renovation has been made, be less than those requirements found in the 1971 "Minimum and Desired Standards and Regulations" for "Homes for the Aged and Infirm", copies of which are available at the Division of Health Service Regulation at no cost;	C 101		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

[Signature]

Executive Director

6/13/18

STATE FORM

6899

XKYT21

If continuation sheet 1 of 4

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL092161	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 05/16/2018
NAME OF PROVIDER OR SUPPLIER WALTONWOOD CARY PARKWAY		STREET ADDRESS, CITY, STATE, ZIP CODE 750 SE CARY PARKWAY CARY, NC 27511		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 101	Continued From page 1 This Rule is not met as evidenced by: 1-Based on observations, this facility has failed to meet the building code requirement in effect at the time of construction regarding Special Locking Systems. The 2009 NC State Building Code-Section 407.9.3.3.4 requires an on/off emergency switch(s) to be located within 3 feet of the door which shall not depend on relays or other electronics to interrupt power. Findings on 03/15/2018: The following locations are magnetically locked doors in the SCU that have momentary switches. Momentary switches automatically re-lock and depend on electronics to interrupt power to the magnets: (a) Fitness Center Room (b) Salon (c) Housekeeping	C 101		
C 189	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1-Based on observation, this facility has failed to maintain the building components in a safe and operating condition.	C 189	6/6/18 As requested, the momentary switches are replaced with mushroom style on/off buttons in locations.	

Division of Health Service Regulation
STATE FORM

6899

XKYT21

If continuation sheet 2 of 4

Phil Nube Executive Director 6/13/18

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL092161	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 05/16/2018
NAME OF PROVIDER OR SUPPLIER WALTONWOOD CARY PARKWAY		STREET ADDRESS, CITY, STATE, ZIP CODE 750 SE CARY PARKWAY CARY, NC 27511		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 2 Findings on 05/16/2018: The Main Kitchen entry door from the Hall does not latch properly due to damage to the door frame on the hinge side of the door. 2-Based on observation, this facility has failed to maintain the building components in a safe and operating condition. Findings on 05/16/2018: The attic access metal door assembly is not secured to the ceiling construction to provide fire resistance. 3-Based on observation, this facility has failed to maintain the HVAC components in a safe and operating condition. Findings on 05/16/2018: The return-air grilles in the AI Dining Hall have excessive particulate build-up. 4-Based on observation, this facility has failed to maintain the fire safety components in a safe and operating condition. Findings on 05/16/2018: The escutcheons are not flush to the ceiling in the AI Dining Hall. 5-Based on observation, this facility has failed to maintain the fire safety components in a safe and operating condition. Findings on 05/16/2018: There is a ceiling penetration that is not fire protected due to a cable installation in Room C-127.	C 189	5/16/18 To ensure the door latches continuously, the door closer was moved over and properly adjusted. 5/16/18 The attic access metal door assembly is secured tightly to the ceiling. 5/17/18 All particulate build-ups have been successfully removed from all air return grilles. 5/21/18 All sprinkler head escutcheons have been adjusted to fit flush against the ceiling. 5/21/18 Penetration around cable is properly sealed off using an approved fire barrier caulk.	

Division of Health Service Regulation
STATE FORM

6899

XKYT21

If continuation sheet 3 of 4

Walter M. H. Executive Director 6/13/18

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL092161	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING: _____	(X3) DATE SURVEY COMPLETED 05/16/2018
NAME OF PROVIDER OR SUPPLIER WALTONWOOD CARY PARKWAY		STREET ADDRESS, CITY, STATE, ZIP CODE 750 SE CARY PARKWAY CARY, NC 27511		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Continued From page 3	C 199		
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1-Based on observation, this facility has failed to exhaust ventilation at the rate of two CFM's per square foot. Findings on 05/16/2018: The mechanical ventilation system is not operational in the Laundry/Room 1039.	C 199	5/21/18 The switch for the ventilation system in the section of the building including the laundry room and Room 1039 was found in the off position in the attic. After the switch was turned on, no other problems were found.	

Division of Health Service Regulation
STATE FORM

6899

XKYT21

If continuation sheet 4 of 4

Julie White 6/13/18
Executive Director