Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	The Hampton Alzheimers Community	***Provider Number***	001946
Address	1617 SE TALTON AVE ,	***Approval Status***	Approved
City, State, Zip	Vancouver, WA 98684	***Facility Type***	Residential Care

On 07/28/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative

Angie Rush
Signature

Angie Rush Executive Director
Print Name and Title

Deputy State Fire Marshal Nicholas Wolden
1823 BAKER WAY
Kelso WA 98626
(360) 852-0966

Nicholas D. Wolden
Signature

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Initials of Authorized Facility Representative: _____

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	The Hampton Alzheimers Community	***Provider Number***	001946
Address	1617 SE TALTON AVE ,	***Approval Status***	Disapproved
City, State, Zip	Vancouver, WA	***Facility Type***	Residential Care

On 03/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
1 Clearance From Ignition Sources	
Clearance between ignition sources, such as luminaries, heaters, flame-producing devices and combustible materials, shall be maintained in an approved manner. (IFC 0305.1 2021)	Combustibles found placed against heaters in room 5,6,7, sprinkler riser room, east court conference room
2 Open electrical terminations	
Open junction boxes and open-wiring splices shall be prohibited. Approved covers shall be provided for all switch and electrical outlet boxes. (IFC 603.2.2, 2021)	
3 Working Space and Clearance	
Working space and clearances. Working space around electrical equipment shall be provided in accordance with Section 110.26 of NFPA 70 for electrical equipment rated 1,000 volts or less, and Section 110.32 of NFPA 70 for electrical equipment rated over 1,000 volts. The minimum required working space shall be not less than 30 inches (762 mm) in width, 36 inches (914 mm) in depth and 78 inches (1981 mm) in height in front of electrical service equipment. Where the electrical service equipment is wider than 30 inches (762 mm), the minimum working space shall be not less than the width of the equipment. Storage of materials shall not be located within the designated working space. (IFC 603.4, 2021)	
4 Installation	
Relocatable power tap cords shall not extend through walls, ceilings, floors, under doors or floor coverings, or be subject to environmental or physical damage. (IFC 603.5.3, 2021)	

Initials of Authorized Facility Representative: AR

This document was prepared by Residential Care Services for the Locator website.

Business Name	The Hampton Alzheimers Community	***Provider Number***	001946
Address	1617 SE TALTON AVE ,	***Approval Status***	Disapproved
City, State, Zip	Vancouver, WA	***Facility Type***	Residential Care

On 03/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
5 Commercial Kitchen Hoods - General	
Commercial kitchen exhaust hoods shall comply with the requirements of the International Mechanical Code. (IFC 606.1 2021)	
6 Owner's Responsibility	
The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space. (IFC 701.6 2021)	Hampton TV room hole found in ceiling Hole in ceiling laundry room Trim around fire window missing in med room
7 Testing	
Horizontal and vertical sliding and rolling fire doors shall be inspected and tested annually to confirm proper operation and full closure. Records of inspections and testing shall be maintained. (IFC 705.2.6 2018)	Facility failed to provide annual roll down fire door test
8 Duct and Air Transfer Openings - Maintaining Protection	
Dampers protecting ducts and air transfer openings shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Other products or materials used to protect the openings for ducts and air transfer openings shall be securely attached to or bonded to the construction containing the duct or air transfer opening, without visible openings through or into the cavity of the construction. Any damaged products or materials protecting duct and air transfer openings shall be repaired, restored or replaced. (IFC 706.1 2018)	Facility failed to provide fire damper testing

Initials of Authorized Facility Representative: AR

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	The Hampton Alzheimers Community	***Provider Number***	001946
Address	1617 SE TALTON AVE ,	***Approval Status***	Disapproved
City, State, Zip	Vancouver, WA	***Facility Type***	Residential Care

On 03/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
9 Testing and Maintenance	
Sprinkler systems shall be tested and maintained in accordance with Section 901. (IFC 903.5 2021)	Fire sprinkler outside dry pendants expired Fire sprinkler report from 12/25 fails to have corrections completed Room 21 sprinkler trim ring missing Facility failed to provide annual forward flow test of sprinkler system
10 Unobstructed and Unobscured	
Manual fire alarm boxes shall be provided with ready access, unobstructed, unobscured and visible at all times. (IFC 907.4.2.6 2021)	
11 Inspection, Testing and Maintenance	
The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained. (IFC 907.8 2021)	
12 Smoke Detector Sensitivity	
Smoke detector sensitivity shall be checked within one year after installation and every alternate year thereafter. After the second calibration test, where sensitivity tests indicate that the detector has remained within its listed and marked sensitivity range (or 4-percent obscuration light grey smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. Where the frequency is extended, records of detector-caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or areas where nuisance alarms show any increase over the previous year, calibration tests shall be performed. (IFC 907.8.3 2021)	Facility failed to provide sensitivity testing of fire alarm system

Initials of Authorized Facility Representative:

This document was prepared by Residential Care Services for the Locator website.

Business Name	The Hampton Alzheimers Community	***Provider Number***	001946
Address	1617 SE TALTON AVE ,	***Approval Status***	Disapproved
City, State, Zip	Vancouver, WA	***Facility Type***	Residential Care

On 03/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
13 Carbon Monoxide Detection - General	
Carbon monoxide detection shall be installed in new buildings in accordance with Sections 915.1.1 through 915.6. Carbon monoxide detection shall be installed in existing buildings in accordance with Chapter 11 of the International Fire Code. (IFC 0915.1 2021 WAC 51-54A)	
14 Bolt Locks	
Manually operated flush bolts or surface bolts are not permitted. Exceptions: 1. On doors not required for egress in individual dwelling units or sleeping units. 2. Where a pair of doors serves a storage or equipment room, manually operated edge- or surface-mounted bolts are permitted on the inactive leaf. 3. Where a pair of doors serves an occupant load of less than 50 persons in a Group B, F or S occupancy, manually operated edge- or surface- mounted bolts are permitted on the inactive leaf. The inactive leaf shall not contain doorknobs, panic bars or similar operating hardware. 4. Where a pair of doors serves a Group B, F or S occupancy, manually operated edge- or surface- mounted bolts are permitted on the inactive leaf provided that such inactive leaf is not needed to meet egress capacity requirements and the building is equipped throughout with an automatic sprinkler system in accordance with Section 903.3.1.1. The inactive leaf shall not contain doorknobs, panic bars or similar operating hardware. 5. Where a pair of doors serves patient care rooms in Group I-2 occupancies, self-latching edge- or surface-mounted bolts are permitted on the inactive leaf provided that the inactive leaf is not needed to meet egress capacity requirements and the inactive leaf shall not contain doorknobs, panic bars or similar operating hardware. (IFC 1010.2.5 2021)	

Initials of Authorized Facility Representative:

This document was prepared by Residential Care Services for the Locator website.

Business Name	The Hampton Alzheimers Community	***Provider Number***	001946
Address	1617 SE TALTON AVE ,	***Approval Status***	Disapproved
City, State, Zip	Vancouver, WA	***Facility Type***	Residential Care

On 03/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
15 Activation Test	
Emergency lighting equipment shall be tested monthly for a duration of not less than 30 seconds. The test shall be performed manually or by an automated self-testing and self-diagnostic routine. Where testing is performed by self-testing and self-diagnostics, a visual inspection of the emergency lighting equipment shall be conducted monthly to identify any equipment displaying a trouble indicator or that has become damaged or otherwise impaired. (IFC 1032.10.1 2021)	
16 Power Test	
Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes. (IFC 1031.10.2 2021)	
17 Obstructions	
A means of egress shall be free from obstructions that would prevent its use, including the accumulation of snow and ice. (IFC 1032.3 2021)	
18 Maintenance	
Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required. (IFC 1203.4 2021)	

Initials of Authorized Facility Representative:_____

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	The Hampton Alzheimers Community	***Provider Number***	001946
Address	1617 SE TALTON AVE ,	***Approval Status***	Disapproved
City, State, Zip	Vancouver, WA	***Facility Type***	Residential Care

On 03/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
19 Fire Drills	
In all Group I, Group E, and Group R2 Occupancies licensed by the state and inspected by the state fire marshal's office, at least twelve planned and unannounced fire drills shall be held every year. (1) Drills shall be conducted quarterly on each shift in Group I and Group R2, Occupancies and monthly in Group E Occupancies to familiarize personnel with signals and emergency action required under varied conditions. (2) A detailed written record of all fire drills shall be maintained and available for inspection. (3) When drills are conducted between 9:00 p.m. and 6:00 a.m., a coded announcement may be used instead of audible alarms.	

Next inspection scheduled on or after: 04/23/2026

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Angie Kvsh

Signature

Angie Kvsh Executive Director

Print Name and Title

Deputy State Fire Marshal Nicholas Wolden
1823 BAKER WAY
Kelso WA 98626
(360) 852-0966

Nicholas D. Wolden

Signature

Initials of Authorized Facility Representative:_____

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	The Hampton Alzheimers Community	***Provider Number***	001946
Address	1617 SE TALTON AVE ,	***Approval Status***	Disapproved
City, State, Zip	Vancouver, WA	***Facility Type***	Residential Care

On 02/05/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation

1 Clearance From Ignition Sources

Clearance between ignition sources, such as luminaries, heaters, flame-producing devices and combustible materials, shall be maintained in an approved manner. (IFC 0305.1 2021)	Combustibles found placed against heaters in room 5,6,7, sprinkler riser room, east court conference room

2 Open electrical terminations

Open junction boxes and open-wiring splices shall be prohibited. Approved covers shall be provided for all switch and electrical outlet boxes. (IFC 603.2.2, 2021)	Open electrical found at gate

3 Working Space and Clearance

Working space and clearances. Working space around electrical equipment shall be provided in accordance with Section 110.26 of NFPA 70 for electrical equipment rated 1,000 volts or less, and Section 110.32 of NFPA 70 for electrical equipment rated over 1,000 volts. The minimum required working space shall be not less than 30 inches (762 mm) in width, 36 inches (914 mm) in depth and 78 inches (1981 mm) in height in front of electrical service equipment. Where the electrical service equipment is wider than 30 inches (762 mm), the minimum working space shall be not less than the width of the equipment. Storage of materials shall not be located within the designated working space. (IFC 603.4, 2021)	Electrical panel found blocked in the following locations: Oxford room Drain snake and ice melt found blocking electrical panel

4 Installation

Relocatable power tap cords shall not extend through walls, ceilings, floors, under doors or floor coverings, or be subject to environmental or physical damage. (IFC 603.5.3, 2021)	Powerstrip found being ran through doorway in laundry room

Initials of Authorized Facility Representative: AK

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	The Hampton Alzheimers Community	***Provider Number***	001946
Address	1617 SE TALTON AVE ,	***Approval Status***	Disapproved
City, State, Zip	Vancouver, WA	***Facility Type***	Residential Care

On 02/05/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
5 Commercial Kitchen Hoods - General	
Commercial kitchen exhaust hoods shall comply with the requirements of the International Mechanical Code. (IFC 606.1 2021)	Broken hood filter in kitchen fan Filters found out of place at time of inspection
6 Owner's Responsibility	
The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space. (IFC 701.6 2021)	Hampton TV room hole found in ceiling Hole in ceiling laundry room Trim around fire window missing in med room
7 Testing	
Horizontal and vertical sliding and rolling fire doors shall be inspected and tested annually to confirm proper operation and full closure. Records of inspections and testing shall be maintained. (IFC 705.2.6 2018)	Facility failed to provide annual roll down fire door test
8 Duct and Air Transfer Openings - Maintaining Protection	
Dampers protecting ducts and air transfer openings shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Other products or materials used to protect the openings for ducts and air transfer openings shall be securely attached to or bonded to the construction containing the duct or air transfer opening, without visible openings through or into the cavity of the construction. Any damaged products or materials protecting duct and air transfer openings shall be repaired, restored or replaced. (IFC 706.1 2018)	Facility failed to provide fire damper testing

Initials of Authorized Facility Representative: _____

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	The Hampton Alzheimers Community	***Provider Number***	001946
Address	1617 SE TALTON AVE ,	***Approval Status***	Disapproved
City, State, Zip	Vancouver, WA	***Facility Type***	Residential Care

On 02/05/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
9 Testing and Maintenance	
Sprinkler systems shall be tested and maintained in accordance with Section 901. (IFC 903.5 2021)	Fire sprinkler outside dry pendants expired Fire sprinkler report from 12/25 fails to have corrections completed Room 21 sprinkler trim ring missing Facility failed to provide annual forward flow test of sprinkler system
10 Unobstructed and Unobscured	
Manual fire alarm boxes shall be provided with ready access, unobstructed, unobscured and visible at all times. (IFC 907.4.2.6 2021)	Physical therapy found to have blocked pull station Classroom blocked pull station
11 Inspection, Testing and Maintenance	
The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained. (IFC 907.8 2021)	Annual fire alarm test failed - Fire alarm panel RED TAGGED- Facility placed in fire watch by City of Vancouver- Fire alarm panel fails to call out per inspection- A fire drill was conducted at time of inspection. When conducting a fire drill the panel called out trouble when a pull station was activated. Additional testing will need to be completed to verify that signals that are being sent out will call out correctly.
12 Smoke Detector Sensitivity	
Smoke detector sensitivity shall be checked within one year after installation and every alternate year thereafter. After the second calibration test, where sensitivity tests indicate that the detector has remained within its listed and marked sensitivity range (or 4-percent obscuration light grey smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. Where the frequency is extended, records of detector-caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or areas where nuisance alarms show any increase over the previous year, calibration tests shall be performed. (IFC 907.8.3 2021)	Facility failed to provide sensitivity testing of fire alarm system

Initials of Authorized Facility Representative: _____

This document was prepared by Residential Care Services for the Locator website.

Business Name	The Hampton Alzheimers Community	***Provider Number***	001946
Address	1617 SE TALTON AVE ,	***Approval Status***	Disapproved
City, State, Zip	Vancouver, WA	***Facility Type***	Residential Care

On 02/05/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
13 Carbon Monoxide Detection - General	
Carbon monoxide detection shall be installed in new buildings in accordance with Sections 915.1.1 through 915.6. Carbon monoxide detection shall be installed in existing buildings in accordance with Chapter 11 of the International Fire Code. (IFC 0915.1 2021 WAC 51-54A)	Facility failed to provide monthly carbon monoxide detector testing
14 Bolt Locks	
Manually operated flush bolts or surface bolts are not permitted. Exceptions: 1. On doors not required for egress in individual dwelling units or sleeping units. 2. Where a pair of doors serves a storage or equipment room, manually operated edge- or surface-mounted bolts are permitted on the inactive leaf. 3. Where a pair of doors serves an occupant load of less than 50 persons in a Group B, F or S occupancy, manually operated edge- or surface- mounted bolts are permitted on the inactive leaf. The inactive leaf shall not contain doorknobs, panic bars or similar operating hardware. 4. Where a pair of doors serves a Group B, F or S occupancy, manually operated edge- or surface- mounted bolts are permitted on the inactive leaf provided that such inactive leaf is not needed to meet egress capacity requirements and the building is equipped throughout with an automatic sprinkler system in accordance with Section 903.3.1.1. The inactive leaf shall not contain doorknobs, panic bars or similar operating hardware. 5. Where a pair of doors serves patient care rooms in Group I-2 occupancies, self-latching edge- or surface-mounted bolts are permitted on the inactive leaf provided that the inactive leaf is not needed to meet egress capacity requirements and the inactive leaf shall not contain doorknobs, panic bars or similar operating hardware. (IFC 1010.2.5 2021)	Deadbolt lock shall be removed from classroom entrance door

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative:

Business Name	The Hampton Alzheimers Community	***Provider Number***	001946
Address	1617 SE TALTON AVE ,	***Approval Status***	Disapproved
City, State, Zip	Vancouver, WA	***Facility Type***	Residential Care

On 02/05/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
15 Activation Test	
Emergency lighting equipment shall be tested monthly for a duration of not less than 30 seconds. The test shall be performed manually or by an automated self-testing and self-diagnostic routine. Where testing is performed by self-testing and self-diagnostics, a visual inspection of the emergency lighting equipment shall be conducted monthly to identify any equipment displaying a trouble indicator or that has become damaged or otherwise impaired. (IFC 1032.10.1 2021)	Facility failed to provide monthly test records
16 Power Test	
Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes. (IFC 1031.10.2 2021)	Facility failed to provide annual test records
17 Obstructions	
A means of egress shall be free from obstructions that would prevent its use, including the accumulation of snow and ice. (IFC 1032.3 2021)	Physical therapy room found to have egress blocked Obstructed exit by room 22
18 Maintenance	
Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required. (IFC 1203.4 2021)	Facility failed to provide weekly and monthly generator testing

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	The Hampton Alzheimers Community	***Provider Number***	001946
Address	1617 SE TALTON AVE ,	***Approval Status***	Disapproved
City, State, Zip	Vancouver, WA	***Facility Type***	Residential Care

On 02/05/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
19 Fire Drills	
In all Group I, Group E, and Group R2 Occupancies licensed by the state and inspected by the state fire marshal's office, at least twelve planned and unannounced fire drills shall be held every year. (1) Drills shall be conducted quarterly on each shift in Group I and Group R2, Occupancies and monthly in Group E Occupancies to familiarize personnel with signals and emergency action required under varied conditions. (2) A detailed written record of all fire drills shall be maintained and available for inspection. (3) When drills are conducted between 9:00 p.m. and 6:00 a.m., a coded announcement may be used instead of audible alarms.	Facility failed to provide fire drills for the following periods Day shift swing shift second quarter Swing shift and night shift fourth quarter

Next inspection scheduled on or after: 03/07/2026

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Angie Rush Executive Director

Print Name and Title

Deputy State Fire Marshal Nicholas Wolden
1823 BAKER WAY
Kelso WA 98626
(360) 852-0966

Signature

Initials of Authorized Facility Representative:

This document was prepared by Residential Care Services for the Locator website.