**Washington State Patrol**
**Fire Protection Bureau**
Phone: (360) 596-3900

| | | | |
|---|---|---|---|
| ***Business Name*** | Everett Heritage Court | ***Provider Number*** | 2612 |
| ***Address*** | 4230 COLBY , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Everett, WA 98203 | ***Facility Type*** | Residential Care |

On 08/12/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|

**1 Ceiling Clearance**

| | |
|---|---|
| Storage shall be maintained 2 feet (610 mm) or more below the ceiling in nonsprinklered areas of buildings or not less than 18 inches (457<br>mm) below sprinkler head deflectors in sprinklered areas of buildings.<br>Exceptions:<br>1. The 2-foot (610 mm) ceiling clearance is not required for storage along walls in nonsprinklered areas of buildings.<br>2. The 18-inch (457 mm) ceiling clearance is not required for storage along walls in areas of buildings equipped with an automatic sprinkler system in<br>accordance with Section 903.3.1.1, 903.3.1.2 or 903.3.1.3.<br><br>(IFC 315.2.1 2021) | Corrected |

**2 Cleaning**

| | |
|---|---|
| Hoods, grease-removal devices, fans, ducts and other appurtenances shall be cleaned at intervals as required by Sections 606.3.3.1 through 606.3.3.3.<br><br>(IFC 606.3.3 2021) | Corrected |

**3 Door Operation**

| | |
|---|---|
| Swinging fire doors shall close from the full-open position and latch automatically.<br><br>(IFC 705.2.4 2021) | 1. The fire door would not latch when closed from the fully open position in resident room number 1.<br><br>2. The fire door would not latch when closed from the fully open position in resident room number 34. |

**4 Testing and Maintenance**

| | |
|---|---|
| Sprinkler systems shall be tested and maintained in accordance with Section 901.<br><br>(IFC 903.5 2021) | Facility was unable to provide documentation for the annual forward flow test. |

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____

| | | | |
|---|---|---|---|
| ***Business Name*** | Everett Heritage Court | ***Provider Number*** | 2612 |
| ***Address*** | 4230 COLBY , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Everett, WA 98203 | ***Facility Type*** | Residential Care |

On 08/12/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|

**5 Extinguishing System Service**

| | |
|---|---|
| Automatic fire-extinguishing systems shall be serviced not less frequently than every six months and after activation of the system. Inspection shall be by qualified individuals, and a certificate of inspection shall be forwarded to the fire code official upon completion.<br><br>(IFC 904.13.5.2 2021) | Corrected |

**6 Unobstructed and Unobscured**

| | |
|---|---|
| Portable fire extinguishers shall not be obstructed or obscured from view. In rooms or areas in which visual obstruction cannot be completely avoided, means shall be provided to indicate the locations of extinguishers.<br><br>(IFC 906.6 2021) | Corrected |

**7 Smoke Detector Sensitivity**

| | |
|---|---|
| Smoke detector sensitivity shall be checked within one year after installation and every alternate year thereafter. After the second calibration test, where sensitivity tests indicate that the detector has remained within its listed and marked sensitivity range (or 4-percent obscuration light grey smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. Where the frequency is extended, records of detector-caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or areas where nuisance alarms show any increase over the previous year, calibration tests shall be performed.<br><br>(IFC 907.8.3 2021) | The facility was unable to provide documentation for the automatic fire alarm sensitivity testing. |

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____

| | | | |
|---|---|---|---|
| ***Business Name*** | Everett Heritage Court | ***Provider Number*** | 2612 |
| ***Address*** | 4230 COLBY , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Everett, WA 98203 | ***Facility Type*** | Residential Care |

On 08/12/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|

**8 Unlatching**

| | |
|---|---|
| The unlatching of any door or leaf for egress shall require not more than one motion in a single linear or rotational direction to release all latching and all locking devices.<br>Exceptions:<br>1. Places of detention or restraint.<br>2. Where manually operated bolt locks are permitted by Section 1010.2.5.<br>3. Doors with automatic flush bolts as permitted by Section 1010.2.4, Item 4.<br>4. Doors from individual dwelling units and sleeping units of Group R occupancies as permitted by Section 1010.2.4, Item 5.<br><br>(IFC 1010.2.1 2021) | Corrected |

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____

| | | | |
|---|---|---|---|
| ***Business Name*** | Everett Heritage Court | ***Provider Number*** | 2612 |
| ***Address*** | 4230 COLBY , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Everett, WA 98203 | ***Facility Type*** | Residential Care |

On 08/12/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|

**9 Lock and Latches**

| | |
|---|---|
| Locks and latches shall be permitted to prevent operation of doors where any of the following exists:<br>1. Places of detention or restraint.<br>2. In buildings in occupancy Group A having an occupant load of 300 or less, Groups B, F, M, and S, and in places of religious worship, the main door or doors are permitted to be equipped with key-operated locking devices from the egress side provided:<br>2.1. The locking device is readily distinguishable as locked;<br>2.2. A readily visible sign is posted on the egress side on or adjacent to the door stating: THIS DOOR TO REMAIN UNLOCKED WHEN BUILDING IS OCCUPIED. The sign shall be in letters 1 inch (25 mm) high on a contrasting background; and<br>2.3. The use of the key-operated locking device is revocable by the building official for due cause.<br>3. Where egress doors are used in pairs, approved automatic flush bolts shall be permitted to be used, provided that the door leaf having the automatic flush bolts has no doorknob or surface-mounted hardware.<br>4. Doors from individual dwelling or sleeping units of Group R occupancies having an occupant load of 10 or less are permitted to be equipped with a night latch, dead bolt, or security chain, provided such devices are openable from the inside without the use of a key or a tool.<br>5. Fire doors after the minimum elevated temperature has disabled the unlatching mechanism in accordance with listed fire door test procedures.<br>6. Doors serving roofs not intended to be occupied shall be permitted to be locked preventing entry to the building from the roof.<br>7. Approved, listed locks without delayed egress shall be permitted in Group I-1 condition 2 assisted living facilities licensed under chapter 388-78A WAC and Group I-1 Condition 2 residential treatment facilities licensed under chapter 246-337 WAC by the state of Washington, provided that:<br>7.1. The clinical needs of one or more patients require specialized security measures for their safety.<br>7.2. The doors unlock upon actuation of the automatic sprinkler system or automatic fire detection system. | Corrected |

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____

| | | | |
|---|---|---|---|
| ***Business Name*** | Everett Heritage Court | ***Provider Number*** | 2612 |
| ***Address*** | 4230 COLBY , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Everett, WA 98203 | ***Facility Type*** | Residential Care |

On 08/12/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|
| 7.3. The doors unlock upon loss of electrical power controlling the lock or lock mechanism.<br>7.4. The lock shall be capable of being deactivated by a signal from a switch located in an approved location.<br>7.5. There is a system, such as a keypad and code, in place that allows visitors, staff persons and appropriate residents to exit. Instructions for exiting shall be posted within six feet of the door.<br>8. Other than egress courts, where occupants must egress from an exterior space through the building for means of egress, exit access doors shall be permitted to be equipped with an approved locking device where installed and operated in accordance with all of the following:<br>8.1. The occupant load of the occupied exterior area shall not exceed 300 as determined by IBC Section 1004.<br>8.2. The maximum occupant load shall be posted where required by Section 1004.9. Such sign shall be permanently affixed inside the building and shall be posted in a conspicuous space near all the exit access doorways.<br>8.3. A weatherproof telephone or two-way communication system installed in accordance with Sections 1009.8.1 and 1009.8.2 shall be located adjacent to not less than one required exit access door on the exterior side.<br>8.4. The egress door locking device is readily distinguishable as locked and shall be a key-operated locking device.<br>8.5. A clear window or glazed door opening, not less than 5 square feet (0.46 m2) sq. ft. in area, shall be provided at each exit access door to determine if there are occupants using the outdoor area.<br>8.6. A readily visible durable sign shall be posted on the interior side on or adjacent to each locked required exit access door serving the exterior area stating: THIS DOOR TO REMAIN UNLOCKED WHEN THE OUTDOOR AREA IS OCCUPIED. The letters on the sign shall be not less than 1 inch high on a contrasting background.<br>9. Locking devices are permitted on doors to balconies, decks, or other exterior spaces serving individual dwelling or sleeping units.<br>10. Locking devices are permitted on doors to balconies, | |

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____

| | | | |
|---|---|---|---|
| ***Business Name*** | Everett Heritage Court | ***Provider Number*** | 2612 |
| ***Address*** | 4230 COLBY , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Everett, WA 98203 | ***Facility Type*** | Residential Care |

On 08/12/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|
| decks, or other exterior spaces of 250 square feet or less, serving a private office space.oor.<br><br>(IFC 1010.2.4 2021 WAC 51-54A) | |

**10 Fire Drills**

| | |
|---|---|
| In all Group I, Group E, and Group R2 Occupancies licensed by the state, at least twelve planned and unannounced fire drills shall be held every year. Drills shall be conducted quarterly on each shift in Group I and Group R2, Occupancies and monthly in Group E Occupancies to familiarize personnel with signals and emergency action required under varied conditions. A detailed written record of all fire drills shall be maintained and available for inspection at all times. When drills are conducted between 9:00 p.m. and 6:00 a.m., a coded announcement may be used instead of audible alarms. Fire drills shall include the transmission of a fire alarm signal and simulation of emergency conditions. The fire alarm monitoring company shall be notified prior to the activation of the fire alarm system for drill purposes and again at the conclusion of the transmission and restoration of the fire alarm system to normal mode.<br><br>(WAC 212-12-044) | Corrected |

**Next inspection scheduled on or after: 09/11/2026**

**Right of appeal.** Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Anthony Cozad

*Signature*

Anthony Cozad Maintenance

*Print Name and Title*

Deputy State Fire Marshal Brandon G. Brown
MP 235 SB Interstate 5
Bow WA 98232
(360) 791-7037

*Signature*



Initials of Authorized Facility Representative: _____

This document was prepared by Residential Care Services for the Locator website.

**Washington State Patrol**
**Fire Protection Bureau**
Phone: (360) 596-3900

| | | | |
|---|---|---|---|
| ***Business Name*** | Everett Heritage Court | ***Provider Number*** | 2612 |
| ***Address*** | 4230 COLBY , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Everett, WA 98203 | ***Facility Type*** | Residential Care |

On 07/01/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|

**1 Ceiling Clearance**

| | |
|---|---|
| Storage shall be maintained 2 feet (610 mm) or more below the ceiling in nonsprinklered areas of buildings or not less than 18 inches (457 mm) below sprinkler head deflectors in sprinklered areas of buildings.<br>Exceptions:<br>1. The 2-foot (610 mm) ceiling clearance is not required for storage along walls in nonsprinklered areas of buildings.<br>2. The 18-inch (457 mm) ceiling clearance is not required for storage along walls in areas of buildings equipped with an automatic sprinkler system in accordance with Section 903.3.1.1, 903.3.1.2 or 903.3.1.3.<br><br>(IFC 315.2.1 2021) | The sprinkler was obstructed in the storage closet across from room 22. |

**2 Cleaning**

| | |
|---|---|
| Hoods, grease-removal devices, fans, ducts and other appurtenances shall be cleaned at intervals as required by Sections 606.3.3.1 through 606.3.3.3.<br><br>(IFC 606.3.3 2021) | The facility was unable to provide the second semi-annual hood cleaning documentation. |

**3 Door Operation**

| | |
|---|---|
| Swinging fire doors shall close from the full-open position and latch automatically.<br><br>(IFC 705.2.4 2021) | 1. The fire door would not latch when closed from the fully opened position next to the medical storage room.<br><br>2. The fire door would not latch when closed from the fully open position in resident room number 1.<br><br>3. The fire door would not latch when closed from the fully open position next to room number 25.<br><br>4. The fire door would not latch when closed from the fully open position in the dining room.<br><br>5. The fire door would not latch when closed from the fully open position in resident room number 4.<br><br>6. The fire door would not latch when closed from the fully open position in resident room number 34. |

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____

| | | | |
|---|---|---|---|
| ***Business Name*** | Everett Heritage Court | ***Provider Number*** | 2612 |
| ***Address*** | 4230 COLBY , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Everett, WA 98203 | ***Facility Type*** | Residential Care |

On 07/01/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|
| **4 Testing and Maintenance** | |
| Sprinkler systems shall be tested and maintained in accordance with Section 901.<br><br>(IFC 903.5 2021) | 1. Facility was unable to provide documentation for the annual forward flow test.<br><br>2. As per documentation provided for the annual automatic sprinkler system testing had a deficiency for the main drain being clogged. |
| **5 Extinguishing System Service** | |
| Automatic fire-extinguishing systems shall be serviced not less frequently than every six months and after activation of the system. Inspection shall be by qualified individuals, and a certificate of inspection shall be forwarded to the fire code official upon completion.<br><br>(IFC 904.13.5.2 2021) | 1. The facility was unable to provide documentation for the first semi-annual servicing of the kitchen suppression system.<br><br>2. The facility was unable to provide documentation for the second semi-annual servicing of the kitchen suppression system. |
| **6 Unobstructed and Unobscured** | |
| Portable fire extinguishers shall not be obstructed or obscured from view. In rooms or areas in which visual obstruction cannot be completely avoided, means shall be provided to indicate the locations of extinguishers.<br><br>(IFC 906.6 2021) | A portable fire extinguisher was being blocked by a chair in the dining room. |
| **7 Smoke Detector Sensitivity** | |
| Smoke detector sensitivity shall be checked within one year after installation and every alternate year thereafter. After the second calibration test, where sensitivity tests indicate that the detector has remained within its listed and marked sensitivity range (or 4-percent obscuration light grey smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. Where the frequency is extended, records of detector-caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or areas where nuisance alarms show any increase over the previous year, calibration tests shall be performed.<br><br>(IFC 907.8.3 2021) | The facility was unable to provide documentation for the automatic fire alarm sensitivity testing. |

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____

| | | | |
|---|---|---|---|
| ***Business Name*** | Everett Heritage Court | ***Provider Number*** | 2612 |
| ***Address*** | 4230 COLBY , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Everett, WA 98203 | ***Facility Type*** | Residential Care |

On 07/01/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|
| **8 Unlatching** | |
| The unlatching of any door or leaf for egress shall require not more than one motion in a single linear or rotational direction to release all latching and all locking devices.<br>Exceptions:<br>1. Places of detention or restraint.<br>2. Where manually operated bolt locks are permitted by Section 1010.2.5.<br>3. Doors with automatic flush bolts as permitted by Section 1010.2.4, Item 4.<br>4. Doors from individual dwelling units and sleeping units of Group R occupancies as permitted by Section 1010.2.4, Item 5.<br><br>(IFC 1010.2.1 2021) | A baby gate was blocking emergency egress in room 25. |

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____

| | | | |
|---|---|---|---|
| ***Business Name*** | Everett Heritage Court | ***Provider Number*** | 2612 |
| ***Address*** | 4230 COLBY , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Everett, WA 98203 | ***Facility Type*** | Residential Care |

On 07/01/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|
| **9 Lock and Latches** | |
| Locks and latches shall be permitted to prevent operation of doors where any of the following exists:<br>1. Places of detention or restraint.<br>2. In buildings in occupancy Group A having an occupant load of 300 or less, Groups B, F, M, and S, and in places of religious worship, the main door or doors are permitted to be equipped with key-operated locking devices from the egress side provided:<br>2.1. The locking device is readily distinguishable as locked;<br>2.2. A readily visible sign is posted on the egress side on or adjacent to the door stating: THIS DOOR TO REMAIN UNLOCKED WHEN BUILDING IS OCCUPIED. The sign shall be in letters 1 inch (25 mm) high on a contrasting background; and<br>2.3. The use of the key-operated locking device is revocable by the building official for due cause.<br>3. Where egress doors are used in pairs, approved automatic flush bolts shall be permitted to be used, provided that the door leaf having the automatic flush bolts has no doorknob or surface-mounted hardware.<br>4. Doors from individual dwelling or sleeping units of Group R occupancies having an occupant load of 10 or less are permitted to be equipped with a night latch, dead bolt, or security chain, provided such devices are openable from the inside without the use of a key or a tool.<br>5. Fire doors after the minimum elevated temperature has disabled the unlatching mechanism in accordance with listed fire door test procedures.<br>6. Doors serving roofs not intended to be occupied shall be permitted to be locked preventing entry to the building from the roof.<br>7. Approved, listed locks without delayed egress shall be permitted in Group I-1 condition 2 assisted living facilities licensed under chapter 388-78A WAC and Group I-1 Condition 2 residential treatment facilities licensed under chapter 246-337 WAC by the state of Washington, provided that:<br>7.1. The clinical needs of one or more patients require specialized security measures for their safety.<br>7.2. The doors unlock upon actuation of the automatic sprinkler system or automatic fire detection system. | 1. The emergency exit code was not posted at the rear exit gate.<br><br>2. The emergency exit code was not posted within six feet of the front entry gate. |

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____

**Washington State Patrol**
**Fire Protection Bureau**
Phone: (360) 596-3900

| | | | |
|---|---|---|---|
| ***Business Name*** | Everett Heritage Court | ***Provider Number*** | 2612 |
| ***Address*** | 4230 COLBY , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Everett, WA 98203 | ***Facility Type*** | Residential Care |

On 07/01/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|
| 7.3. The doors unlock upon loss of electrical power controlling the lock or lock mechanism.<br>7.4. The lock shall be capable of being deactivated by a signal from a switch located in an approved location.<br>7.5. There is a system, such as a keypad and code, in place that allows visitors, staff persons and appropriate residents to exit. Instructions for exiting shall be posted within six feet of the door.<br>8. Other than egress courts, where occupants must egress from an exterior space through the building for means of egress, exit access doors shall be permitted to be equipped with an approved locking device where installed and operated in accordance with all of the following:<br>8.1. The occupant load of the occupied exterior area shall not exceed 300 as determined by IBC Section 1004.<br>8.2. The maximum occupant load shall be posted where required by Section 1004.9. Such sign shall be permanently affixed inside the building and shall be posted in a conspicuous space near all the exit access doorways.<br>8.3. A weatherproof telephone or two-way communication system installed in accordance with Sections 1009.8.1 and 1009.8.2 shall be located adjacent to not less than one required exit access door on the exterior side.<br>8.4. The egress door locking device is readily distinguishable as locked and shall be a key-operated locking device.<br>8.5. A clear window or glazed door opening, not less than 5 square feet (0.46 m2) sq. ft. in area, shall be provided at each exit access door to determine if there are occupants using the outdoor area.<br>8.6. A readily visible durable sign shall be posted on the interior side on or adjacent to each locked required exit access door serving the exterior area stating: THIS DOOR TO REMAIN UNLOCKED WHEN THE OUTDOOR AREA IS OCCUPIED. The letters on the sign shall be not less than 1 inch high on a contrasting background.<br>9. Locking devices are permitted on doors to balconies, decks, or other exterior spaces serving individual dwelling or sleeping units.<br>10. Locking devices are permitted on doors to balconies, | |

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____

**Washington State Patrol**
**Fire Protection Bureau**
Phone: (360) 596-3900

| | | | |
|---|---|---|---|
| ***Business Name*** | Everett Heritage Court | ***Provider Number*** | 2612 |
| ***Address*** | 4230 COLBY , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Everett, WA 98203 | ***Facility Type*** | Residential Care |

On 07/01/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|
| decks, or other exterior spaces of 250 square feet or less, serving a private office space.oor.<br><br>(IFC 1010.2.4 2021 WAC 51-54A) | |
| **10 Fire Drills** | |
| In all Group I, Group E, and Group R2 Occupancies licensed by the state, at least twelve planned and unannounced fire drills shall be held every year. Drills shall be conducted quarterly on each shift in Group I and Group R2, Occupancies and monthly in Group E Occupancies to familiarize personnel with signals and emergency action required under varied conditions. A detailed written record of all fire drills shall be maintained and available for inspection at all times. When drills are conducted between 9:00 p.m. and 6:00 a.m., a coded announcement may be used instead of audible alarms. Fire drills shall include the transmission of a fire alarm signal and simulation of emergency conditions. The fire alarm monitoring company shall be notified prior to the activation of the fire alarm system for drill purposes and again at the conclusion of the transmission and restoration of the fire alarm system to normal mode.<br><br>(WAC 212-12-044) | Facility was unable to provide documentation for the completion of twelve planned and unannounced fire drills in the previous 12 months.<br><br>The following Drills are missing.<br><br>1st Shift - Quarter 2 and 3<br><br>2nd Shift - Quarter 3 and 4<br><br>3rd Shift - Quarter 1, 2, and 3 |

**Next inspection scheduled on or after: 07/31/2026**

**Right of appeal.** Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Anthony Cozad
*Signature*

Anthony Cozad Maintenance
*Print Name and Title*

Deputy State Fire Marshal Larisa Hennessy
2803 156TH AVE SE
Bellevue WA 98007
(425) 620-5012

*Signature*



Initials of Authorized Facility Representative: _____

This document was prepared by Residential Care Services for the Locator website.