

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL067023	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 05/28/2025
NAME OF PROVIDER OR SUPPLIER ONSLOW HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 34 MCDANIEL DRIVE JACKSONVILLE, NC 28546		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of Construction Section Biennial Survey by Ryan Meyer conducted on May 28, 2025. Records indicate this facility was first licensed on 09/18/1986 as a Home for the aged. The facility is currently licensed for 120 Beds. Therefore, this facility is required to meet the 1984 Minimum and Desired Standards and Regulations for Homes for the Aged and Disabled; the applicable portions of the 2005 Rules for Adult Care Homes of Seven or More Beds; and the 1978 North Carolina State Building Code (Revision 5) Section 409- Institutional Occupancy- Unrestrained Deficiencies were cited which will require a Plan of Correction.	C 000		
C 188	Electrical Outlets in Wet Locations SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0310 ELECTRICAL OUTLETS All adult care home electrical outlets in wet locations at sinks, bathrooms and outside of building shall have ground fault interrupters. This Rule is not met as evidenced by: 1. Based on observation the facility is not maintaining the electrical components located near a water source in a safe manner. Findings on May 28, 2025 a. There are multiple outlets in the laundry room that are within 6 feet of a water source that are not GFCI protected.	C 188		
C 189	Building Equipment Maintained Safe, Operating	C 189		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL067023	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 05/28/2025
NAME OF PROVIDER OR SUPPLIER ONSLOW HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 34 MCDANIEL DRIVE JACKSONVILLE, NC 28546		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 1 SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation the facility is not maintaining its plumbing system as necessary. Findings on May 28, 2025: a. The ice machine drain does not have the correct 2-inch air gap. 2. Based on observation, this facility has failed to maintain the fire safety components in a safe and operating condition. Findings on May 28, 2025: a. The 200 hallways first set of fire doors has a gap larger than the allowable 1/8". b. The Fire Alarm Panel indicates that AHU-23 has a trouble with its communication relay.	C 189		
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed	C 199		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL067023	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 05/28/2025
NAME OF PROVIDER OR SUPPLIER ONSLOW HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 34 MCDANIEL DRIVE JACKSONVILLE, NC 28546		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 199	Continued From page 2 before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1. Based on observation and interview with the Maintenance Director the facility is not keeping its exhaust fan in operable condition. Exhaust fans that do not operate continuously or that can be turned on when needed could allow for the buildup of odor and moisture. Findings on May 28, 2025: a. The exhaust fans throughout the facility are not operating as required. The exhaust fans have been set to only come on at certain times of the day.	C 199		