




Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Hampton Special Care Tumwater	Provider Number	001579
Address	1400 TROSPER RD SW,	Approval Status	Approved
City, State, Zip	Tumwater, WA	Facility Type	Residential Care

On 02/02/2026 the Office of the State Fire Marshal conducted an inspection at your facility.


All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative


Signature

Gabriel Pantoja Maintenance Director
Print Name and Title

Deputy State Fire Marshal Raul Murcia
PO BOX 42642
Olympia WA 98504
(360) 819-0067


Signature

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Hampton Special Care Tumwater	Provider Number	001579
Address	1400 TROSPER RD SW,	Approval Status	Disapproved
City, State, Zip	Tumwater, WA	Facility Type	Residential Care

On 12/08/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

1 Duct and Air Transfer Openings - Maintaining Protection

Dampers protecting ducts and air transfer openings shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Other products or materials used to protect the openings for ducts and air transfer openings shall be securely attached to or bonded to the construction containing the duct or air transfer opening, without visible openings through or into the cavity of the construction. Any damaged products or materials protecting duct and air transfer openings shall be repaired, restored or replaced.

(IFC 706.1 2018)

Findings during the inspection were:

Fire/smoke damper report from 4/10/2023, Sunset Air, showed deficiencies. Need report showing correction have been made.

2 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901.

(IFC 903.5 2021)

Findings during the inspection were:

Facility failed to provide annual forward flow test for the fire sprinkler backflow.

3 Extinguishing System Service

Automatic fire-extinguishing systems shall be serviced not less frequently than every six months and after activation of the system. Inspection shall be by qualified individuals, and a certificate of inspection shall be forwarded to the fire code official upon completion.

(IFC 904.13.5.2 2021)

Findings during the inspection were:

Facility failed to provide report showing kitchen suppression system is being inspected twice a year.

4 Inspection, Testing and Maintenance

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained.

(IFC 907.8 2021)

Findings during the inspection were:

Facility failed to provide monthly inspection report for battery operated smoke alarms.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Hampton Special Care Tumwater	Provider Number	001579
Address	1400 TROSPER RD SW,	Approval Status	Disapproved
City, State, Zip	Tumwater, WA	Facility Type	Residential Care

On 12/08/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

Next inspection scheduled on or after: 01/08/2026

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative


Signature

Gabriel Pantoja Maintenance Director
Print Name and Title

Deputy State Fire Marshal Raul Murcia
PO BOX 42642
Olympia WA 98504
(360) 819-0067


Signature