Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Channel Point Village	***Provider Number***	2621
Address	907 K ST ,	***Approval Status***	Approved
City, State, Zip	Hoquiam, WA 98550	***Facility Type***	Residential Care

On 07/01/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative

Signature

Reed, Colby (maint Director)
Print Name and Title

Deputy State Fire Marshal Raul Murcia
PO BOX 42642
Olympia WA 98504
(360) 819-0067

Signature

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Initials of Authorized Facility Representative:_____

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Channel Point Village	***Provider Number***	2621
Address	907 K ST ,	***Approval Status***	Disapproved
City, State, Zip	Hoquiam, WA	***Facility Type***	Residential Care

On 12/04/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation

1 Record Keeping

Records shall be maintained of required emergency evacuation drills and include the following information: 1. Identity of the person conducting the drill. 2. Date and time of the drill. 3. Notification method used. 4. Employees on duty and participating. 5. Number of occupants evacuated. 6. Special conditions simulated. 7. Problems encountered. 8. Weather conditions when occupants were evacuated. 9. Time required to accomplish complete evacuation. (IFC 0405.6 2021)	Findings during the inspection were: Facility failed to provide the following documentation; Fire drills shall be conducted once per shift per quarter and documentation shall be kept for the previous 12 months.

2 Hazard Abatement

601.2 Hazard abatement. Operations or conditions deemed unsafe or hazardous by the fire code official shall be abated. Equipment, appliances, materials and systems that are modified or damaged and constitute an electrical shock or fire hazard shall not be used. 601.2.1 Correction of unsafe conditions. The fire code official shall be authorized to require the owner, the owner's authorized agent, operator or occupant of a building or premises to abate or cause to be abated or corrected such unsafe operations or conditions either by repair, rehabilitation, demolition or other approved corrective action in compliance with this code.	Findings during the inspection were: Facility failed to maintain the following; -Broken ground on electrical outlet located across from room 503. Other outlets observed with broken grounds, need a facility wide inspection of electrical outlets.

3 Cleaning

Hoods, grease-removal devices, fans, ducts and other appurtenances shall be cleaned at intervals as required by Sections 606.3.3.1 through 606.3.3.3. (IFC 606.3.3 2021)	Findings during the inspection were: Facility failed to provide the following documentation; -Annual hood cleaning. -Semi-annual hood cleaning.

Initials of Authorized Facility Representative:_____

This document was prepared by Residential Care Services for the Locator website.

Business Name	Channel Point Village	***Provider Number***	2621
Address	907 K ST ,	***Approval Status***	Disapproved
City, State, Zip	Hoquiam, WA	***Facility Type***	Residential Care

On 12/04/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
4 Owner's Responsibility	
The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space. (IFC 701.6 2021)	Findings during the inspection were: Facility failed to provide the following documentation; -Annual inspection of all fire-resistance-rated construction (fire wall inspection). There was ceiling penetration in laundry room located by kitchen.
5 Duct and Air Transfer Openings - Maintaining Protection	
Dampers protecting ducts and air transfer openings shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Other products or materials used to protect the openings for ducts and air transfer openings shall be securely attached to or bonded to the construction containing the duct or air transfer opening, without visible openings through or into the cavity of the construction. Any damaged products or materials protecting duct and air transfer openings shall be repaired, restored or replaced. (IFC 706.1 2018)	Findings during the inspection were: Facility failed to provide the following documentation; -Fire/smoke damper 4-year annual inspection.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative:_____

Business Name	Channel Point Village	***Provider Number***	2621
Address	907 K ST ,	***Approval Status***	Disapproved
City, State, Zip	Hoquiam, WA	***Facility Type***	Residential Care

On 12/04/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
6 Testing and Maintenance	
Sprinkler systems shall be tested and maintained in accordance with Section 901. (IFC 903.5 2021)	Findings during the inspection were: Facility failed to provide the following documentation for the fire sprinkler system; -Annual inspection. -Annual trip test. -Annual forward flow test for the backflow. -Quarterly inspections. Fire alarm in yellow status, outside water flow bell does not operate. Red sprinkler head box located in fire sprinkler riser room was missing a wrench. Sprinkler heads loaded with debris in Salon and in Kitchen area.
7 Extinguishing System Service	
Automatic fire-extinguishing systems shall be serviced not less frequently than every six months and after activation of the system. Inspection shall be by qualified individuals, and a certificate of inspection shall be forwarded to the fire code official upon completion. (IFC 904.13.5.2 2021)	Findings during the inspection were: Facility failed to provide the following documentation; -Annual inspection for kitchen suppression system. -Semi-annual inspection for kitchen suppression system.

Initials of Authorized Facility Representative:_____

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Channel Point Village	***Provider Number***	2621
Address	907 K ST ,	***Approval Status***	Disapproved
City, State, Zip	Hoquiam, WA	***Facility Type***	Residential Care

On 12/04/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation

8 Portable Fire Extinguishers - General Requirements

Portable fire extinguishers shall be selected, installed and maintained in accordance with this section and NFPA 10. Exceptions: 1. The distance of travel to reach an extinguisher shall not apply The travel distance to reach an extinguisher shall not apply to the spectator seating portions of Group A-5 occupancies. 2. Thirty-day inspections shall not be required and maintenance shall be allowed to be once every three years for dry-chemical or halogenated agent portable fire extinguishers that are supervised by a listed and approved electronic monitoring device, provided that all of the following conditions are met: 2.1. Electronic monitoring shall confirm that extinguishers are properly positioned, properly charged and unobstructed. 2.2. Loss of power or circuit continuity to the electronic monitoring device shall initiate a trouble signal. 2.3. The extinguishers shall be installed inside of a building or cabinet in a noncorrosive environment. 2.4. Electronic monitoring devices and supervisory circuits shall be tested every 3 years when extinguisher maintenance is performed. 2.5. A written log of required hydrostatic test dates for extinguishers shall be maintained by the owner to verify that hydrostatic tests are conducted at the frequency required by NFPA 10. 3. In Group I-3, portable fire extinguishers shall be permitted to be located at staff locations. (IFC 906.2 2021)	Findings during the inspection were: Facility failed to provide the following documentation; -Monthly inspection of all portable fire extinguishers. Storage room by room 102 has an unsecured portable fire extinguisher. Kitchen ABC (red) portable fire extinguisher mounted on wall is over 5 feet.

9 Inspection, Testing and Maintenance

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained. (IFC 907.8 2021)	Findings during the inspection were: Facility failed to provide the following documentation; -Annual fire alarm report.

Initials of Authorized Facility Representative:_____

This document was prepared by Residential Care Services for the Locator website.

Business Name	Channel Point Village	***Provider Number***	2621
Address	907 K ST ,	***Approval Status***	Disapproved
City, State, Zip	Hoquiam, WA	***Facility Type***	Residential Care

On 12/04/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
10 Smoke Detector Sensitivity	
Smoke detector sensitivity shall be checked within one year after installation and every alternate year thereafter. After the second calibration test, where sensitivity tests indicate that the detector has remained within its listed and marked sensitivity range (or 4-percent obscuration light grey smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. Where the frequency is extended, records of detector-caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or areas where nuisance alarms show any increase over the previous year, calibration tests shall be performed. (IFC 907.8.3 2021)	Findings during the inspection were: Facility failed to provide the following documentation; -Sensitivity test for all fire alarm smoke detectors.
11 Maintenance	
Carbon monoxide alarms and carbon monoxide detection systems shall be maintained in accordance with NFPA 72. Carbon monoxide alarms and carbon monoxide detectors that become inoperable or begin producing end-of-life signals shall be replaced. (IFC 915.6 2021 WAC)	Findings during the inspection were: Facility failed to provide documentation showing carbon monoxide alarms are being inspected per manufacturer's standard.
12 Activation Test	
Emergency lighting equipment shall be tested monthly for a duration of not less than 30 seconds. The test shall be performed manually or by an automated self-testing and self-diagnostic routine. Where testing is performed by self-testing and self-diagnostics, a visual inspection of the emergency lighting equipment shall be conducted monthly to identify any equipment displaying a trouble indicator or that has become damaged or otherwise impaired. (IFC 1032.10.1 2021)	Findings during the inspection were: Facility failed to provide the following documentation; -Monthly 30-second activation test for exits signs and emergency lights.
13 Power Test	
Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes. (IFC 1031.10.2 2021)	Findings during the inspection were: Facility failed to provide the following documentation; -Annual 1.5 hour power test for exits signs and emergency lights.

Initials of Authorized Facility Representative:_____

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Channel Point Village	***Provider Number***	2621
Address	907 K ST ,	***Approval Status***	Disapproved
City, State, Zip	Hoquiam, WA	***Facility Type***	Residential Care

On 12/04/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
14 Maintenance	
Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required. (IFC 1203.4 2021)	Findings during the inspection were: Facility failed to provide the following documentation; -Generator annual servicing. -Log of weekly inspections. -Log of monthly 30-minute full load test.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative:_____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Channel Point Village	***Provider Number***	2621
Address	907 K ST ,	***Approval Status***	Disapproved
City, State, Zip	Hoquiam, WA	***Facility Type***	Residential Care

On 12/04/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
15 NFPA 80 Fire Door Inspection and Testing	
5.2.1 Inspection and Testing. Upon completin of the installation, door, shutters, and window assemblies shall be inspected and tested in accordance with 5.2.4. 5.2.4 Periodic Inspection and Testing. 5.2.4.1 Periodic inspections and testing shall be performed not less than annually. 5.2.2.4 A record of all inspections and testing shall be provided that includes, but is not limited to, the following information: 1. Date of inspection 2. Name of facility 3. Address of facility 4. Name of person(s) performing inspections and testing 5. Company name and address of inspecting company 6. Signature of inspector of record 7. Individual record of each inspected and tested fire door assembly 8. Opening identifier and location of each inspected and tested fire door assembly 9. Type and description of each inspected and tested fire door assembly 10. Verification of visual inspection and functional operation 11. Listing of deficiencies in accordance with 5.2.3, Section 5.3, and Section 5.4 And the following hall be checked: 1. Labels are clearly visible and legible 2. No open holes or breaks exist in surfaces of wither the door or frame 3. Glazing, vision light frames, and glazing beads are intact and securely fastened in place, if so equipped. 4. The door, frame, hinges, hardware, and non combustible threshold are secured, aligned and in working order with no visible, signs of damage 5. No parts are missing or broken 6. Door clearances do not exceed clearances listed in 4.8.4 and 6.3.1.7 7. The self-closing device is operational,: that is, the active door completely closes when operated from the full open position 8. If a coordinator is installed, the inactive lead close before the active lead	Findings during the inspection were: Facility failed to provide the following documentation; -Annual fire door inspection. Doors with self-closers throught the facility, incliding memeory care were being held open by door wedges. Electrical room across from room 303 in memory care door failed to latch. 700 hall stair case 1st floor exit failed to latch.

Initials of Authorized Facility Representative:_____

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Channel Point Village	***Provider Number***	2621
Address	907 K ST ,	***Approval Status***	Disapproved
City, State, Zip	Hoquiam, WA	***Facility Type***	Residential Care

On 12/04/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
9. Latching hardware operates and secures the door when it is in the closed positon 10. Auxiliary hardware items that interfere or prohibit operation are not installed on the door or frame 11. No field modification to the door assembly have been preformed that void the label. 12. Meeting edge protection, gasketing and edge seals where required, are inspected to verify their presence and intertie 13. Signage affixed to a door meets the requirements listed in 4.1.4	

Next inspection scheduled on or after: 01/08/2026

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Reed, Colby (Maint. Director)
Print Name and Title

Deputy State Fire Marshal Raul Murcia
PO BOX 42642
Olympia WA 98504
(360) 819-0067

Signature

Initials of Authorized Facility Representative:_____

This document was prepared by Residential Care Services for the Locator website.