Wisconsin Department of Health Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	0018080	A. BUILDING: _____ B. WING _____	R 08/28/2026

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ELIZABETH I	**516 ELIZABETH STREET WATERFORD, WI 53185**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{M 000}	INITIAL COMMENTS On 08/28/2026, Surveyor conducted a verification visit at Elizabeth I. One deficiency was identified. Under statutory provisions of Wis. Stat. Ch. 50, a $200 revisit fee will be assessed. Census: 3	{M 000}		
M 278	88.05(3)(b) FREE OF HAZARDS The home shall be free from hazards and kept uncluttered and free of dangerous substances, insects and rodents. This Rule is not met as evidenced by: Based on observation and interviews, the provider did not ensure the facility was free from environmental hazards. The dryer was vented with semi-rigid material. Findings include: According to FEMA (Federal Emergency Management Agency), "Facts about home clothes dryer fires...2,900 home clothes dryer fires are reported each year and cause an estimated 5 deaths, 100 injuries, and $35 million in property loss...Maintenance-Inspect the venting system behind the dryer to ensure it is not damaged or restricted. Put a covering on outside wall dampers to keep out rain, snow, and dirt.	M 278		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE | TITLE | (X6) DATE

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	0018080	A. BUILDING: _____ B. WING _____	R 08/28/2026

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ELIZABETH I	**516 ELIZABETH STREET WATERFORD, WI 53185**

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
M 278	Continued From page 1 Make sure the outdoor vent covering opens when the dryer is on. Replace coiled-wire foil or plastic venting with rigid, non-ribbed metal duct. (Source: https://www.usfa.fema.gov/statistics/reports/fire-causes/ (Retrieval date 08/28/2026))" On 08/28/2026 at 12:17 p.m., Surveyor observed the dryer's vent was made of semi-rigid material approximately 5-inches long. On 08/28/2026 at 12:35 p.m., Surveyor shared above observations with Administrator A. Administrator A acknowledged the semi-rigid dryer vent was not in compliance. Administrator A stated the maintenance man misunderstood the kind of ridged vented material that was required on the dryer units. Administrator A stated s/he would work with maintenance to get that corrected immediately.	M 278		