Healthcare Licensing and Surveys

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	ALF006	A. BUILDING: _____ B. WING _____	08/25/2026

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ASPEN WIND ASSISTED LIVING COMMUNITY	4010 NORTH COLLEGE DRIVE CHEYENNE, WY 82001

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
	S 000. General Comments A Life Safety Code Survey was conducted by Healthcare Licensing and Surveys on 08/25/2026. The facility was a single story fully sprinklered building of Type V (111) construction built in 1998 with an addition in 2010. The building was equipped with a supervised automatic wet sprinkler system, and an addressable fire alarm system. The facility had a capacity of 94 licensed beds with a census of 72 residents. Wyoming Department of Health, Rules and Regulations for Licensure of Assisted Living Facilities Chapter 4, Section 10 Life Safety and Electrical Safety. The requirements in the Department of Health Chapter III, Construction Rules for Health Facilities apply. (II) Assisted Living Facilities operating prior to the effective date of these rules, shall meet the Life Safety Code of the National Fire Protection Association that was in effect at the time the facility was licensed as an Assisted Living Facility. All references are based on the requirements of the 1994 and 2006 NFPA 101, Life Safety Code, New Residential Board and Care unless otherwise noted.	S 000		
S8003	NFPA Life Safety - Nfpa Means of Egress Components NFPA 101 Means of Egress Components This State Rule and Regulation is not met as evidenced by: NFPA Life Safety - NFPA Means of Egress Components	S8003		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE: Michelle McDonald — TITLE: Executive Director — (X6) DATE: 9/17/2026

Healthcare Licensing and Surveys

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	ALF006	A. BUILDING: _____ B. WING _____	08/25/2026

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
ASPEN WIND ASSISTED LIVING COMMUNITY	4010 NORTH COLLEGE DRIVE CHEYENNE, WY 82001

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
S8003	Continued From page 1 NFPA 101 Means of Egress Components This State Rule and Regulation is not met as evidence by: Based on observation and staff interview, the facility failed to maintain means of egress components in accordance with NFPA 101, Life Safety Code. Failure to maintain means of egress components as required could result in delayed egress during an emergency leading to injury or death. The deficiency affected all residents, staff, and visitors. The findings were: Observation on 08/25/2026 at 10:35 AM at emergency exit door # 100A was found inoperable. When the door was tested from the egress side, the door failed to initiate the opening process, preventing occupants from exiting from the required means of egress. Interview with the maintenance staff at the time of observation confirmed the deficiency, and indicated that he was aware of the requirement. Interview with the administrator at the time of exit confirmed the deficiency. Ref: 1994 NFPA 101, Section 22-3.2, 5-2.1, 5-2.1.5	S8003	An inspection was scheduled on 8/27/26 performed by fire protection service company. The alarm on the emergency exit door #100A was tested, re-set and was in functional capacity immediately afterwards. Routine inspections on emergency exit doors are scheduled as required by state guidelines.	