STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	ASL510208	A. BUILDING: _____ B. WING _____	C 11/19/2025

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
IMBODEN CREEK GARDENS	185 W IMBODEN DR DECATUR, IL 62521

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
A 000	Initial Comment Complaint Investigation Complaint 25611259/IL198614 Complaint can be partially substantiated. Type 2 Violation cited at 295.9040 a)	A 000		
A9040	Section 295.9040 Environmental Requirements This Regulation is not met as evidenced by: Section 295.9040 Environmental Requirements a) The establishment shall be kept in a clean, safe and orderly condition and in good repair. Based on record review and interview the establishment failed to ensure their heating system will be repaired and working in a timely manner; creating a substantial probability of harm to residents. Findings include: On 11-19-2025, at approximately 1:30pm, E1, Administrator, states that the front lobby is the only area affected. E1 states that all resident rooms have heat and that they have portable heaters available if needed. E1 also states that they move residents to different rooms when there are call light, heating, or cooling issues noted and that they are able to move wall units and exchange for ones that are working. The establishment's 11-17-2025 proposed bid contains documentation that the repair is for a unit that services the Lobby and Dining areas.	A9040		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	ASL510208	A. BUILDING: _____ B. WING _____	C 11/19/2025

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
IMBODEN CREEK GARDENS	185 W IMBODEN DR DECATUR, IL 62521

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
A9040	Continued From page 1 Documentation also includes that there is a three to four week wait time on the parts. On 11-17-2025 at approximately 12:30pm, upon entrance to establishment to begin investigation, E1, Administrator, states that they just got a bid approved to fix the heat. Temperatures in the establishment were observed during the investigation. All areas were noted to be comfortable and thermostats were checked where available. The lowest thermostat reading during the investigation was 68 degrees Fahrenheit in the lobby on 11-19-2025 at 10:03am.	A9040		