**Washington State Patrol**
**Fire Protection Bureau**
Phone: (360) 596-3900

| | | | |
|---|---|---|---|
| ***Business Name*** | Washington Odd Fellows Home (BH) | ***Provider Number*** | 000125 |
| ***Address*** | 534 BOYER , | ***Approval Status*** | Approved |
| ***City, State, Zip*** | Walla Walla, WA 99362 | ***Facility Type*** | Residential Care |

On 09/15/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|

**1 Admin - (ITM) Inspection, Testing, & Maintenance**

| | |
|---|---|
| Any citation that requires inspection, testing, or maintenance (ITM) is required to have the testing completed, paper results delivered, and any deficiencies found during the ITM corrected before the citation is cleared." | On 07/21/2026 an unannounced Fire and Life Safety Code inspection was conducted at Washington Odd Fellows Home by a representative of the Washington State Patrol, State Fire Marshal's Office to determine compliance with all applicable codes. The following deficiencies were cited as a result of this inspections. |

**2 Ceiling Clearance**

| | |
|---|---|
| Storage shall be maintained 2 feet (610 mm) or more below the ceiling in nonsprinklered areas of buildings or not less than 18 inches (457<br>mm) below sprinkler head deflectors in sprinklered areas of buildings.<br>Exceptions:<br>1. The 2-foot (610 mm) ceiling clearance is not required for storage along walls in nonsprinklered areas of buildings.<br>2. The 18-inch (457 mm) ceiling clearance is not required for storage along walls in areas of buildings equipped with an automatic sprinkler system in<br>accordance with Section 903.3.1.1, 903.3.1.2 or 903.3.1.3.<br><br>(IFC 315.2.1 2021) | The following violation was observed:<br><br>-The 2nd floor resident laundry storage closet did not have 24" clearance to ceiling and was not sprinkled. *CORRECTED*<br>-Both sprinkler heads in the main kitchen freezer were impeded by 18". *CORRECTED* |

**3 Abatement of Electrical Hazards**

| | |
|---|---|
| Abatement of unsafe conditions and electrical hazards. Conditions that constitute an electrical shock or fire hazard shall be abated..<br><br>(IFC 603.2 2021) | The following violation was observed:<br><br>- The electrical panels in the ALF activities by storage were unlocked. *CORRECTED* |



Initials of Authorized Facility Representative:

This document was prepared by Residential Care Services for the Locator website.

**Washington State Patrol**
**Fire Protection Bureau**
Phone: (360) 596-3900

| | | | |
|---|---|---|---|
| ***Business Name*** | Washington Odd Fellows Home (BH) | ***Provider Number*** | 000125 |
| ***Address*** | 534 BOYER , | ***Approval Status*** | Approved |
| ***City, State, Zip*** | Walla Walla, WA 99362 | ***Facility Type*** | Residential Care |

On 09/15/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|

**4 Extension Cords**

| | |
|---|---|
| Extension cords. Extension cords shall not be a substitute for permanent wiring and shall be listed and labeled in accordance with UL 817. Extension cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances. Extension cords marked for indoor use shall not be used outdoors..<br><br>(IFC 603.6 2021) | The following violation was observed:<br><br>-The 2nd floor nurses station had a extension cord being used as permanent wiring. *CORRECTED* |

**5 Penetrations - Maintaining Protection**

| | |
|---|---|
| Materials and firestop systems used to protect membrane and through penetrations in fire-resistance-rated construction and construction installed to resist the passage of smoke shall be maintained. The materials and firestop systems shall be securely attached to or bonded to the construction being penetrated with no openings visible through or into the cavity of the construction. Where the system design number is known, the system shall be inspected to the listing criteria and manufacturer's installation instructions.<br><br>(IFC 703.1 2021) | The following violation was observed:<br><br>-The main kitchens office had penetrations through wall. *CORRECTED* |

**6 Door Operation**

| | |
|---|---|
| Swinging fire doors shall close from the full-open position and latch automatically.<br><br>(IFC 705.2.4 2021) | The following violation was observed:<br><br>-The south fire door to the auditorium would not latch from a fully opened position. *CORRECTED*<br>-The business office managers fire door would not close and latch from a fully opened position. *CORRECTED*<br>-The fire door to north dry storage entrance would not close and latch from a fully opened position. *CORRECTED* |



Initials of Authorized Facility Representative:

This document was prepared by Residential Care Services for the Locator website.

| | | | |
|---|---|---|---|
| ***Business Name*** | Washington Odd Fellows Home (BH) | ***Provider Number*** | 000125 |
| ***Address*** | 534 BOYER , | ***Approval Status*** | Approved |
| ***City, State, Zip*** | Walla Walla, WA 99362 | ***Facility Type*** | Residential Care |

On 09/15/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|
| **7 Testing and Maintenance** | |
| Sprinkler systems shall be tested and maintained in accordance with Section 901.<br><br>(IFC 903.5 2021) | The following violation was observed:<br><br>-The sprinkler head in hallway near activities had what appeared to be paint on it. *CORRECTED*<br>-The sprinkler head in storage of 2nd floor clinical room had paint on it. *CORRECTED*<br>-The sprinkler valve in 2nd floor janitors closet had several canes hanging from it. *CORRECTED* |
| **8 Portable Fire Extinguishers - General Requirements** | |
| Portable fire extinguishers shall be selected, installed and maintained in accordance with this section and NFPA 10.<br><br>Exceptions:<br>1. The distance of travel to reach an extinguisher shall not apply The travel distance to reach an extinguisher shall not apply to the spectator seating portions of Group A-5 occupancies.<br>2. Thirty-day inspections shall not be required and maintenance shall be allowed to be once every three years for dry-chemical or halogenated agent portable fire extinguishers that are supervised by a listed and approved electronic monitoring device, provided that all of the following conditions are met:<br>2.1. Electronic monitoring shall confirm that extinguishers are properly positioned, properly charged and unobstructed.<br>2.2. Loss of power or circuit continuity to the electronic monitoring device shall initiate a trouble signal.<br>2.3. The extinguishers shall be installed inside of a building or cabinet in a noncorrosive environment.<br>2.4. Electronic monitoring devices and supervisory circuits shall be tested every 3 years when extinguisher maintenance is performed.<br>2.5. A written log of required hydrostatic test dates for extinguishers shall be maintained by the owner to verify that hydrostatic tests are conducted at the frequency required by NFPA 10.<br>3. In Group I-3, portable fire extinguishers shall be permitted to be located at staff locations.<br><br>(IFC 906.2 2021) | The following violation was observed:<br><br>-The fire extinguisher in HRS training mechanical area expired 04/2025. *CORRECTED* |



Initials of Authorized Facility Representative: RH

This document was prepared by Residential Care Services for the Locator website.

**Washington State Patrol**
**Fire Protection Bureau**
Phone: (360) 596-3900

| | | | |
|---|---|---|---|
| ***Business Name*** | Washington Odd Fellows Home (BH) | ***Provider Number*** | 000125 |
| ***Address*** | 534 BOYER , | ***Approval Status*** | Approved |
| ***City, State, Zip*** | Walla Walla, WA 99362 | ***Facility Type*** | Residential Care |

On 09/15/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|
| **9 Installation and Monitoring** | |
| Fire alarm system shall be installed and monitored in accordance with Sections 907.6.1 through 907.6.6.3 and NFPA 72.<br><br>(IFC 907.6 2021) | The following violation was observed:<br><br>-The fire alarm circuit located in the 2nd floor mechanical did not have breaker lock installed. *CORRECTED* |
| **10 Inspection, Testing and Maintenance** | |
| The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained.<br><br>(IFC 907.8 2021) | The facility was unable to provide documentation for the following:<br><br>-The facility failed to provide documentation of an annual fire alarm inspection in the last twelve months. The semi annual was provided dated 01-29-2026. *CORRECTED* |
| **11 Power Test** | |
| Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes.<br><br>(IFC 1031.10.2 2021) | The facility was unable to provide documentation for the following:<br><br>-The 90 min annual exit and emergency lighting power test had not been performed. *CORRECTED*<br><br>All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected. |



Initials of Authorized Facility Representative: RH

This document was prepared by Residential Care Services for the Locator website.

**Washington State Patrol**
**Fire Protection Bureau**
Phone: (360) 596-3900

| | | | |
|---|---|---|---|
| ***Business Name*** | Washington Odd Fellows Home (BH) | ***Provider Number*** | 000125 |
| ***Address*** | 534 BOYER , | ***Approval Status*** | Approved |
| ***City, State, Zip*** | Walla Walla, WA 99362 | ***Facility Type*** | Residential Care |

On 09/15/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|
| **12 Fire Drills** | |
| In all Group I, Group E, and Group R2 Occupancies licensed by the state, at least twelve planned and unannounced fire drills shall be held every year. Drills shall be conducted quarterly on each shift in Group I and Group R2, Occupancies and monthly in Group E Occupancies to familiarize personnel with signals and emergency action required under varied conditions. A detailed written record of all fire drills shall be maintained and available for inspection at all times. When drills are conducted between 9:00 p.m. and 6:00 a.m., a coded announcement may be used instead of audible alarms. Fire drills shall include the transmission of a fire alarm signal and simulation of emergency conditions. The fire alarm monitoring company shall be notified prior to the activation of the fire alarm system for drill purposes and again at the conclusion of the transmission and restoration of the fire alarm system to normal mode.<br><br>(WAC 212-12-044) | Facility was unable to provide documentation that the following fire drills were performed or documented correctly:<br><br>- The last 12 months of NOC shift fire drills were documented as silent drills. The documentation also had the boxes checked that the fire alarm functioned properly. Between the hours of 2100 - 0600 hours fire drills do not require activation of fire alarm. Education was given on properly documenting for silent drills. *CORRECTED* |

**Next inspection scheduled on or after: 07/31/2027**

**Right of appeal.** Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

*Signature*

PETE HARSIN Director of facilities

*Print Name and Title*

Deputy State Fire Marshal Andrea Ely
2715 RUDKIN RD
Union Gap WA
(509) 531-3384

Andrea Ely Digitally signed by Andrea Ely Date: 2026.09.16 11:21:06 -07'00' Adobe Acrobat Reader version: 2026.002.21869

*Signature*



Initials of Authorized Facility Representative:

This document was prepared by Residential Care Services for the Locator website.

**Washington State Patrol**
**Fire Protection Bureau**
Phone: (360) 596-3900

| | | | |
|---|---|---|---|
| ***Business Name*** | Washington Odd Fellows Home (BH) | ***Provider Number*** | 000125 |
| ***Address*** | 534 BOYER , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Walla Walla, WA 99362 | ***Facility Type*** | Residential Care |

On 07/21/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|

**1 Admin - (ITM) Inspection, Testing, & Maintenance**

| | |
|---|---|
| Any citation that requires inspection, testing, or maintenance (ITM) is required to have the testing completed, paper results delivered, and any deficiencies found during the ITM corrected before the citation is cleared." | On 07/21/2026 an unannounced Fire and Life Safety Code inspection was conducted at Washington Odd Fellows Home by a representative of the Washington State Patrol, State Fire Marshal's Office to determine compliance with all applicable codes. The following deficiencies were cited as a result of this inspections. |

**2 Ceiling Clearance**

| | |
|---|---|
| Storage shall be maintained 2 feet (610 mm) or more below the ceiling in nonsprinklered areas of buildings or not less than 18 inches (457<br>mm) below sprinkler head deflectors in sprinklered areas of buildings.<br>Exceptions:<br>1. The 2-foot (610 mm) ceiling clearance is not required for storage along walls in nonsprinklered areas of buildings.<br>2. The 18-inch (457 mm) ceiling clearance is not required for storage along walls in areas of buildings equipped with an automatic sprinkler system in<br>accordance with Section 903.3.1.1, 903.3.1.2 or 903.3.1.3.<br><br>(IFC 315.2.1 2021) | The following violation was observed:<br><br>-The 2nd floor resident laundry storage closet did not have 24" clearance to ceiling and was not sprinkled.<br>-Both sprinkler heads in the main kitchen freezer were impeded by 18" |

**3 Abatement of Electrical Hazards**

| | |
|---|---|
| Abatement of unsafe conditions and electrical hazards. Conditions that constitute an electrical shock or fire hazard shall be abated..<br><br>(IFC 603.2 2021) | The following violation was observed:<br><br>- The electrical panels in the ALF activities by storage were unlocked. |



Initials of Authorized Facility Representative: RH

This document was prepared by Residential Care Services for the Locator website.

**Washington State Patrol**
**Fire Protection Bureau**
Phone: (360) 596-3900

| | | | |
|---|---|---|---|
| ***Business Name*** | Washington Odd Fellows Home (BH) | ***Provider Number*** | 000125 |
| ***Address*** | 534 BOYER , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Walla Walla, WA 99362 | ***Facility Type*** | Residential Care |

On 07/21/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|

**4 Extension Cords**

| | |
|---|---|
| Extension cords. Extension cords shall not be a substitute for permanent wiring and shall be listed and labeled in accordance with UL 817. Extension cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances. Extension cords marked for indoor use shall not be used outdoors..<br><br>(IFC 603.6 2021) | The following violation was observed:<br><br>-The 2nd floor nurses station had a extension cord being used as permanent wiring. |

**5 Penetrations - Maintaining Protection**

| | |
|---|---|
| Materials and firestop systems used to protect membrane and through penetrations in fire-resistance-rated construction and construction installed to resist the passage of smoke shall be maintained. The materials and firestop systems shall be securely attached to or bonded to the construction being penetrated with no openings visible through or into the cavity of the construction. Where the system design number is known, the system shall be inspected to the listing criteria and manufacturer's installation instructions.<br><br>(IFC 703.1 2021) | The following violation was observed:<br><br>-The main kitchens office had penetrations through wall. |

**6 Door Operation**

| | |
|---|---|
| Swinging fire doors shall close from the full-open position and latch automatically.<br><br>(IFC 705.2.4 2021) | The following violation was observed:<br><br>-The south fire door to the auditorium would not latch from a fully opened position.<br>-The business office managers fire door would not close and latch from a fully opened position.<br>-The fire door to north dry storage entrance would not close and latch from a fully opened position. |



Initials of Authorized Facility Representative:

This document was prepared by Residential Care Services for the Locator website.

| | | | |
|---|---|---|---|
| ***Business Name*** | Washington Odd Fellows Home (BH) | ***Provider Number*** | 000125 |
| ***Address*** | 534 BOYER , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Walla Walla, WA 99362 | ***Facility Type*** | Residential Care |

On 07/21/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|

**7 Testing and Maintenance**

| | |
|---|---|
| Sprinkler systems shall be tested and maintained in accordance with Section 901.<br><br>(IFC 903.5 2021) | The following violation was observed:<br><br>-The sprinkler head in hallway near activities had what appeared to be paint on it.<br>-The sprinkler head in storage of 2nd floor clinical room had paint on it.<br>-The sprinkler valve in 2nd floor janitors closet had several canes hanging from it. |

**8 Portable Fire Extinguishers - General Requirements**

| | |
|---|---|
| Portable fire extinguishers shall be selected, installed and maintained in accordance with this section and NFPA 10.<br><br>Exceptions:<br>1. The distance of travel to reach an extinguisher shall not apply The travel distance to reach an extinguisher shall not apply to the spectator seating portions of Group A-5 occupancies.<br>2. Thirty-day inspections shall not be required and maintenance shall be allowed to be once every three years for dry-chemical or halogenated agent portable fire extinguishers that are supervised by a listed and approved electronic monitoring device, provided that all of the following conditions are met:<br>2.1. Electronic monitoring shall confirm that extinguishers are properly positioned, properly charged and unobstructed.<br>2.2. Loss of power or circuit continuity to the electronic monitoring device shall initiate a trouble signal.<br>2.3. The extinguishers shall be installed inside of a building or cabinet in a noncorrosive environment.<br>2.4. Electronic monitoring devices and supervisory circuits shall be tested every 3 years when extinguisher maintenance is performed.<br>2.5. A written log of required hydrostatic test dates for extinguishers shall be maintained by the owner to verify that hydrostatic tests are conducted at the frequency required by NFPA 10.<br>3. In Group I-3, portable fire extinguishers shall be permitted to be located at staff locations.<br><br>(IFC 906.2 2021) | The following violation was observed:<br><br>-The fire extinguisher in HRS training mechanical area expired 04/2025. |



Initials of Authorized Facility Representative: RH

This document was prepared by Residential Care Services for the Locator website.

**Washington State Patrol**
**Fire Protection Bureau**
Phone: (360) 596-3900

| | | | |
|---|---|---|---|
| ***Business Name*** | Washington Odd Fellows Home (BH) | ***Provider Number*** | 000125 |
| ***Address*** | 534 BOYER , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Walla Walla, WA 99362 | ***Facility Type*** | Residential Care |

On 07/21/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|

**9 Installation and Monitoring**

| | |
|---|---|
| Fire alarm system shall be installed and monitored in accordance with Sections 907.6.1 through 907.6.6.3 and NFPA 72.<br><br>(IFC 907.6 2021) | The following violation was observed:<br><br>-The fire alarm circuit located in the 2nd floor mechanical did not have breaker lock installed. |

**10 Inspection, Testing and Maintenance**

| | |
|---|---|
| The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained.<br><br>(IFC 907.8 2021) | The facility was unable to provide documentation for the following:<br><br>-The facility failed to provide documentation of an annual fire alarm inspection in the last twelve months. The semi annual was provided dated 01-29-2026.<br><br>All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected. |

**11 Power Test**

| | |
|---|---|
| Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes.<br><br>(IFC 1031.10.2 2021) | The facility was unable to provide documentation for the following:<br><br>-The 90 min annual exit and emergency lighting power test had not been performed.<br><br>All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected. |



Initials of Authorized Facility Representative: PH

This document was prepared by Residential Care Services for the Locator website.

**Washington State Patrol**
**Fire Protection Bureau**
Phone: (360) 596-3900

| | | | |
|---|---|---|---|
| ***Business Name*** | Washington Odd Fellows Home (BH) | ***Provider Number*** | 000125 |
| ***Address*** | 534 BOYER , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Walla Walla, WA 99362 | ***Facility Type*** | Residential Care |

On 07/21/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|
| **12 Fire Drills** | |
| In all Group I, Group E, and Group R2 Occupancies licensed by the state, at least twelve planned and unannounced fire drills shall be held every year. Drills shall be conducted quarterly on each shift in Group I and Group R2, Occupancies and monthly in Group E Occupancies to familiarize personnel with signals and emergency action required under varied conditions. A detailed written record of all fire drills shall be maintained and available for inspection at all times. When drills are conducted between 9:00 p.m. and 6:00 a.m., a coded announcement may be used instead of audible alarms. Fire drills shall include the transmission of a fire alarm signal and simulation of emergency conditions. The fire alarm monitoring company shall be notified prior to the activation of the fire alarm system for drill purposes and again at the conclusion of the transmission and restoration of the fire alarm system to normal mode.<br><br>(WAC 212-12-044) | Facility was unable to provide documentation that the following fire drills were performed or documented correctly:<br><br>- The last 12 months of NOC shift fire drills were documented as silent drills. The documentation also had the boxes checked that the fire alarm functioned properly. Between the hours of 2100 - 0600 hours fire drills do not require activation of fire alarm. Education was given on properly documenting for silent drills. |

**Next inspection scheduled on or after: 08/20/2026**

**Right of appeal.** Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Pete Harsin — *Signature*

PETE HARSIN Director of Facilities — Print Name and Title

Deputy State Fire Marshal Alan Harlan
2803 156TH AVE SE
Bellevue WA 98007
(425) 495-7121

Alan Harlan
Digitally signed by Alan Harlan
Date: 2026.07.21 16:00:02 -07'00'
*Signature*



Initials of Authorized Facility Representative: _____

This document was prepared by Residential Care Services for the Locator website.