Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Ovenell Home ALF Inc	***Provider Number***	2172
Address	625 Washington ,	***Approval Status***	Approved
City, State, Zip	Burlington, WA 98233	***Facility Type***	Residential Care

On 08/05/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative

Signature *Print Name and Title*

Deputy State Fire Marshal Brandon G. Brown
MP 235 SB Interstate 5
Bow WA 98232
(360) 791-7037

Signature

This document was prepared by Residential Care Services for the Locator website.

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Ovenell Home ALF Inc	***Provider Number***	2172
Address	625 Washington ,	***Approval Status***	Disapproved
City, State, Zip	Burlington, WA 98233	***Facility Type***	Residential Care

On 06/29/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation

1 Open electrical terminations

Open junction boxes and open-wiring splices shall be prohibited. Approved covers shall be provided for all switch and electrical outlet boxes. (IFC 603.2.2, 2021)	There is an open junction box on the wall in the stairwell exposing the inner electrical wiring.

2 Internally Illuminated Exit Signs

Electrically powered, self-luminous and photoluminescent exit signs shall be listed and labeled in accordance with UL 924 and shall be installed in accordance with the manufacturer's instructions and Section 1203. Exit signs shall be illuminated at all times. (IFC 1013.5 2021)	1. The internally illuminated exit sign in the library would not illuminate when the activation test button was pushed or on normal power. 2. The internally illuminated exit sign/emergency light combo near room 1 would not illuminate when the activation test button was pushed or on normal power. 3. The internally illuminated exit sign near room 11 would not illuminate when the activation test button was pushed or on normal power. 4. The internally illuminated exit sign in room 11 would not illuminate when the activation test button was pushed or on normal power.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Ovenell Home ALF Inc	***Provider Number***	2172
Address	625 Washington ,	***Approval Status***	Disapproved
City, State, Zip	Burlington, WA 98233	***Facility Type***	Residential Care

On 06/29/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
3 Securing Compressed Gas Containers, Cylinders and Tanks	
Compressed gas containers, cylinders and tanks shall be secured to prevent falling caused by contact, vibration or seismic activity. Securing of compressed gas containers, cylinders and tanks shall be by one of the following methods: 1. Securing containers, cylinders and tanks to a fixed object with one or more restraints. 2. Securing containers, cylinders and tanks on a cart or other mobile device designed for the movement of compressed gas containers, cylinders or tanks. 3. Nesting of compressed gas containers, cylinders and tanks at container filling or servicing facilities or in sellers' warehouses not open to the public. Nesting shall be allowed provided that the nested containers, cylinders or tanks, if dislodged, do not obstruct the required means of egress. 4. Securing of compressed gas containers, cylinders and tanks to or within a rack, framework, cabinet or similar assembly designed for such use. Exception: Compressed gas containers, cylinders and tanks in the process of examination, filling, transport or servicing. (IFC 5303.5.3 2021)	Oxygen cylinder in the records room is not secured to prevent the cylinder from falling.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Ovenell Home ALF Inc	***Provider Number***	2172
Address	625 Washington ,	***Approval Status***	Disapproved
City, State, Zip	Burlington, WA 98233	***Facility Type***	Residential Care

On 06/29/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation

Next inspection scheduled on or after: 07/29/2026

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Tony Zimmermann Admin
Print Name and Title

Deputy State Fire Marshal Brandon G. Brown
MP 235 SB Interstate 5
Bow WA 98232
(360) 791-7037

Brandon Brown Digitally signed by Brandon Brown
Date: 2026.06.29 16:59:54 -07'00'
Signature

Initials of Authorized Facility Representative: _____

This document was prepared by Residential Care Services for the Locator website.