Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Woodland Village	***Provider Number***	2512
Address	2100 SW WOODLAND CIR ,	***Approval Status***	Approved
City, State, Zip	Chehalis, WA 98532	***Facility Type***	Residential Care

On 10/05/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative

Signature

Jeni S. Webster

Print Name and Title

Deputy State Fire Marshal Jason Van Gorkum
2502 112 ST E
Tacoma WA 984455104
(509) 406-7209

Signature

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Initials of Authorized Facility Representative: _____

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Woodland Village	***Provider Number***	2512
Address	2100 SW WOODLAND CIR ,	***Approval Status***	Disapproved
City, State, Zip	Chehalis, WA 98532	***Facility Type***	Residential Care

On 07/22/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation

1 Equipment Rooms

Combustible material shall not be stored in boiler rooms, mechanical rooms, electrical equipment rooms or in fire command centers as specified in Section 508.1.5. (IFC 315.2.3 2021)	The facility failed to remove combustible material from equipment room/maintenance shop. ✓

2 Open electrical terminations

Open junction boxes and open-wiring splices shall be prohibited. Approved covers shall be provided for all switch and electrical outlet boxes. (IFC 603.2.2, 2021)	The following electrical junction box covers were found to be broken or missing: Open electrical junction box in the break room Open electrical junction box outside the kitchen by the hood vent Broken light switch in the kitchen exiting hallway Broken light switch in the kitchen janitors closet ✓ Broken electrical outlet in room 248 ✓ Fire sprinkler riser low air sensor cover removed ✓ Water flow cover removed in fire sprinkler riser room

3 Extension Cords

Extension cords. Extension cords shall not be a substitute for permanent wiring and shall be listed and labeled in accordance with UL 817. Extension cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances. Extension cords marked for indoor use shall not be used outdoors.. (IFC 603.6 2021)	Extension cords found to be used as permanent wiring in the following locations: The solarium behind the couch ✓ The activity room on the first floor ✓ ✓

Initials of Authorized Facility Representative: _____

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Woodland Village	***Provider Number***	2512
Address	2100 SW WOODLAND CIR ,	***Approval Status***	Disapproved
City, State, Zip	Chehalis, WA 98532	***Facility Type***	Residential Care

On 07/22/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
4 Cleaning	
Hoods, grease-removal devices, fans, ducts and other appurtenances shall be cleaned at intervals as required by Sections 606.3.3.1 through 606.3.3.3. (IFC 606.3.3 2021)	The facility failed to provide semi-annual hood system cleaning 2/22/26 / 8/24/26
5 Owner's Responsibility	
The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space. (IFC 701.6 2021)	The following areas were found to have penetrations in fire resistance rated construction Break room lst floor under table Fire sprinkler riser room floor 1 ceiling and wall Elevator mechanical room found to have holes in walls and none approved fire stop material Boiler room found to have none approved fire stop foam
6 Inspection and Maintenance	
Opening protectives in fire-resistance-rated assemblies shall be inspected and maintained in accordance with NFPA 80. Opening protectives in smoke barriers shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Openings in smoke partitions shall be inspected and maintained in accordance with NFPA 105. Fire doors and smoke and draft control doors shall not be blocked, obstructed, or otherwise made inoperable. Fusible links shall be replaced promptly whenever fused or damaged. Opening protectives and smoke and draft control doors shall not be modified. (IFC 705.2 2021)	Facility failed to provide an annual fire door inspection report that includes all required elements of NFPA 80 The following doors were found to have items attached: Resident room 240 Resident room 237 Activities office in memory care hole in door

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Woodland Village	***Provider Number***	2512
Address	2100 SW WOODLAND CIR ,	***Approval Status***	Disapproved
City, State, Zip	Chehalis, WA 98532	***Facility Type***	Residential Care

On 07/22/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
7 Testing and Maintenance	
Sprinkler systems shall be tested and maintained in accordance with Section 901. (IFC 903.5 2021)	Facility failed to provide the following reports: ✓ Annual forward flow inspection report Cintas 8/26/26 Dry pendant sprinkler heads found to be expired ✓ Fire sprinkler trim ring missing in solarium and dining room ✓ Standard response and quick response sprinkler heads mixed in solarium

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Woodland Village	***Provider Number***	2512
Address	2100 SW WOODLAND CIR ,	***Approval Status***	Disapproved
City, State, Zip	Chehalis, WA 98532	***Facility Type***	Residential Care

On 07/22/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
8 Portable Fire Extinguishers - General Requirements	
Portable fire extinguishers shall be selected, installed and maintained in accordance with this section and NFPA 10. Exceptions: 1. The distance of travel to reach an extinguisher shall not apply The travel distance to reach an extinguisher shall not apply to the spectator seating portions of Group A-5 occupancies. 2. Thirty-day inspections shall not be required and maintenance shall be allowed to be once every three years for dry-chemical or halogenated agent portable fire extinguishers that are supervised by a listed and approved electronic monitoring device, provided that all of the following conditions are met: 2.1. Electronic monitoring shall confirm that extinguishers are properly positioned, properly charged and unobstructed. 2.2. Loss of power or circuit continuity to the electronic monitoring device shall initiate a trouble signal. 2.3. The extinguishers shall be installed inside of a building or cabinet in a noncorrosive environment. 2.4. Electronic monitoring devices and supervisory circuits shall be tested every 3 years when extinguisher maintenance is performed. 2.5. A written log of required hydrostatic test dates for extinguishers shall be maintained by the owner to verify that hydrostatic tests are conducted at the frequency required by NFPA 10. 3. In Group I-3, portable fire extinguishers shall be permitted to be located at staff locations. (IFC 906.2 2021)	Facility failed to conduct monthly fire extinguisher inspection in the following locations: Hallway near main laundry Mechanical room/ boiler room ✓

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Woodland Village	***Provider Number***	2512
Address	2100 SW WOODLAND CIR ,	***Approval Status***	Disapproved
City, State, Zip	Chehalis, WA 98532	***Facility Type***	Residential Care

On 07/22/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
9 Activation Test	
Emergency lighting equipment shall be tested monthly for a duration of not less than 30 seconds. The test shall be performed manually or by an automated self-testing and self-diagnostic routine. Where testing is performed by self-testing and self-diagnostics, a visual inspection of the emergency lighting equipment shall be conducted monthly to identify any equipment displaying a trouble indicator or that has become damaged or otherwise impaired. (IFC 1032.10.1 2021)	Facility failed to provide monthly emergency light testing report ✓
10 Power Test	
Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes. (IFC 1031.10.2 2021)	Facility failed to provide annual emergency light testing ✓ 1/12/2026
11 Securing Compressed Gas Containers, Cylinders and Tanks	
Compressed gas containers, cylinders and tanks shall be secured to prevent falling caused by contact, vibration or seismic activity. Securing of compressed gas containers, cylinders and tanks shall be by one of the following methods: 1. Securing containers, cylinders and tanks to a fixed object with one or more restraints. 2. Securing containers, cylinders and tanks on a cart or other mobile device designed for the movement of compressed gas containers, cylinders or tanks. 3. Nesting of compressed gas containers, cylinders and tanks at container filling or servicing facilities or in sellers' warehouses not open to the public. Nesting shall be allowed provided that the nested containers, cylinders or tanks, if dislodged, do not obstruct the required means of egress. 4. Securing of compressed gas containers, cylinders and tanks to or within a rack, framework, cabinet or similar assembly designed for such use. Exception: Compressed gas containers, cylinders and tanks in the process of examination, filling, transport or servicing. (IFC 5303.5.3 2021)	Unsecured oxygen storage tank in room 248 ✓

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Woodland Village	***Provider Number***	2512
Address	2100 SW WOODLAND CIR ,	***Approval Status***	Disapproved
City, State, Zip	Chehalis, WA 98532	***Facility Type***	Residential Care

On 07/22/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
12 Fire Drills	
In all Group I, Group E, and Group R2 Occupancies licensed by the state and inspected by the state fire marshal's office, at least twelve planned and unannounced fire drills shall be held every year. (1) Drills shall be conducted quarterly on each shift in Group I and Group R2, Occupancies and monthly in Group E Occupancies to familiarize personnel with signals and emergency action required under varied conditions. (2) A detailed written record of all fire drills shall be maintained and available for inspection. (3) When drills are conducted between 9:00 p.m. and 6:00 a.m., a coded announcement may be used instead of audible alarms.	The facility failed to provide the following fire drill reports: First quarter 2026: Night shift Second quarter 2026: Night shift Third quarter 2025: Day shift and night shift Fourth quarter 2025: Swing shift ✓

Next inspection scheduled on or after: 08/21/2026

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

[signature]
Signature

Kiersten Milton. Executive Director
Print Name and Title

Deputy State Fire Marshal Nicholas Wolden /Jason Vanbuskirk
1823 BAKER WAY
Kelso WA 98626
(360) 852-0966

[signature]
Signature

Initials of Authorized Facility Representative: _____

This document was prepared by Residential Care Services for the Locator website.