**Washington State Patrol**
**Fire Protection Bureau**
Phone: (360) 596-3900

| | | | |
|---|---|---|---|
| ***Business Name*** | Murano Senior Living | ***Provider Number*** | 2521 |
| ***Address*** | 620 TERRY AVE , | ***Approval Status*** | Approved |
| ***City, State, Zip*** | Seattle, WA 98104 | ***Facility Type*** | Residential Care |

On 10/06/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

**All violations noted during previous related inspection(s) have been corrected.**

Owner or Owner's Representative

*Signature*

Marshall Nisbet 10-6-26
*Print Name and Title*

Deputy State Fire Marshal Alan Harlan
2803 156TH AVE SE
Bellevue WA 98007
(425) 495-7121

*Signature*

This document was prepared by Residential Care Services for the Locator website.

**Right of appeal.** Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.



Initials of Authorized Facility Representative: _____

**Washington State Patrol**
**Fire Protection Bureau**
Phone: (360) 596-3900

| | | | |
|---|---|---|---|
| ***Business Name*** | Murano Senior Living | ***Provider Number*** | 2521 |
| ***Address*** | 620 TERRY AVE , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Seattle, WA 98104 | ***Facility Type*** | Residential Care |

On 03/23/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|

**1 Administration**

**2 Abatement of Electrical Hazards**

| | |
|---|---|
| Abatement of unsafe conditions and electrical hazards. Conditions that constitute an electrical shock or fire hazard shall be abated..<br><br>(IFC 603.2 2021) | Corrected |

**3 Listing**

| | |
|---|---|
| .5.1 Listing. Relocatable power taps shall be listed in accordance with UL 1363. Current taps shall be listed and labeled in accordance with UL 498A.<br><br>(IFC 0603.5.1, 2021) | Corrected |

**4 Application and Use**

| | |
|---|---|
| 603.5.2 Application and use. Relocatable power taps and current taps shall be directly connected to a permanently installed receptacle.<br>Exceptions:<br>1. Where approved for use in a Group A occupancy or in a meeting room in a Group B occupancy, not more than five relocatable power taps shall be permitted to be connected together or connected to an extension cord for temporary use to supply power to electronic equipment.<br>2. Current taps and relocatable power taps shall not be required to connect directly to a permanently installed receptacle outlet where used for 90 days or less for the purpose of testing the performance of such devices.<br><br>(IFC 603.5.2, 2021) | Findings during the inspection were:<br><br>1. Two relocatable power taps were not plugged into a permanently installed receptacle in the IT room. |

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____

| | | | |
|---|---|---|---|
| ***Business Name*** | Murano Senior Living | ***Provider Number*** | 2521 |
| ***Address*** | 620 TERRY AVE , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Seattle, WA 98104 | ***Facility Type*** | Residential Care |

On 03/23/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|
| **5 Extension Cords** | |
| Extension cords. Extension cords shall not be a substitute for permanent wiring and shall be listed and labeled in accordance with UL 817. Extension cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances. Extension cords marked for indoor use shall not be used outdoors..<br><br>(IFC 603.6 2021) | Corrected |
| **6 Listed and Labeled** | |
| Only listed and labeled portable, electric space heaters shall be used.<br><br>(IFC 603.9.1, 2021) | Corrected |
| **7 Operations, Inspection and Maintenance** | |
| Commercial cooking systems shall be operated, inspected, and maintained in accordance with Sections 606.3.1 through 606.3.4 and Chapter 12 of NFPA 96.<br><br>(IFC 606.3 2021 WAC 51-54A) | Corrected |
| **8 Grease Accumulation** | |
| f during the inspection it is found that hoods, grease-removal devices, fans, ducts or other appurtenances have an accumu ation of grease, such components shall be cleaned in accordance with ANSI/IKECA C10.<br><br>(IFC 606.3.3.2 2021) | Corrected |

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____

| | | | |
|---|---|---|---|
| ***Business Name*** | Murano Senior Living | ***Provider Number*** | 2521 |
| ***Address*** | 620 TERRY AVE , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Seattle, WA 98104 | ***Facility Type*** | Residential Care |

On 03/23/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|
| **9 Appliance Connection to Building Piping** | |
| Gas-fired commercial cooking appliances installed on casters and appliances that are moved for cleaning and sanitation purposes shall be connected to the piping system with an appliance connector listed as complying with ANSI Z21.69/CSA 6.16. The commercial cooking appliance connector installation shall be configured in accordance with the manufacturer's installation instructions. Movement of appliances with casters shall be limited by a restraining device installed in accordance with the connector and appliance manufacturer's instructions.<br><br>(IFC 606.4 2021) | Findings during the inspection were:<br><br>Kitchen appliances connected to natural gas and mounted on casters do not have the required restraining device installed. |
| **10 Penetrations - Maintaining Protection** | |
| Materials and firestop systems used to protect membrane and through penetrations in fire-resistance-rated construction and construction installed to resist the passage of smoke shall be maintained. The materials and firestop systems shall be securely attached to or bonded to the construction being penetrated with no openings visible through or into the cavity of the construction. Where the system design number is known, the system shall be inspected to the listing criteria and manufacturer's installation instructions.<br><br>(IFC 703.1 2021) | Corrected |
| **11 Inspection and Maintenance** | |
| Opening protectives in fire-resistance-rated assemblies shall be inspected and maintained in accordance with NFPA 80. Opening protectives in smoke barriers shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Openings in smoke partitions shall be inspected and maintained in accordance with NFPA 105. Fire doors and smoke and draft control doors shall not be blocked, obstructed, or otherwise made inoperable. Fusible links shall be replaced promptly whenever fused or damaged. Opening protectives and smoke and draft control doors shall not be modified.<br><br>(IFC 705.2 2021) | Corrected |

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____

| | | | |
|---|---|---|---|
| ***Business Name*** | Murano Senior Living | ***Provider Number*** | 2521 |
| ***Address*** | 620 TERRY AVE , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Seattle, WA 98104 | ***Facility Type*** | Residential Care |

On 03/23/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|
| **12 Door Operation** | |
| Swinging fire doors shall close from the full-open position and latch automatically.<br><br>(IFC 705.2.4 2021) | Findings during the inspection were:<br><br>The following fire doors did not latch during testing:<br><br>1. Rubbish and Recycle door in the Refuse/ Recycle near room 202<br>2. Gym entry |
| **13 Testing and Maintenance** | |
| Sprinkler systems shall be tested and maintained in accordance with Section 901.<br><br>(IFC 903.5 2021) | Corrected |

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____

| | | | |
|---|---|---|---|
| ***Business Name*** | Murano Senior Living | ***Provider Number*** | 2521 |
| ***Address*** | 620 TERRY AVE , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Seattle, WA 98104 | ***Facility Type*** | Residential Care |

On 03/23/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|

**14 Portable Fire Extinguishers - General Requirements**

| | |
|---|---|
| Portable fire extinguishers shall be selected, installed and maintained in accordance with this section and NFPA 10.<br><br>Exceptions:<br>1. The d stance of travel to reach an extinguisher shall not apply The travel distance to reach an extinguisher shall not apply to the spectator seating portions of Group A-5 occupancies.<br>2. Thirty-day inspections shall not be required and maintenance shall be allowed to be once every three years for dry-chemical or halogenated agent portable fire extinguishers are supervised by a listed and approved electronic monitoring device, provided that all of the following conditions are met:<br>2.1. Electronic monitoring shall confirm that extinguishers are properly positioned, properly charged and unobstructed.<br>2.2. Loss of power or circuit continuity to the electronic monitoring device shall initiate a trouble signal.<br>2.3. The extinguishers shall be installed inside of a building or cabinet in a noncorrosive environment.<br>2.4. Electronic monitoring devices and supervisory circuits shall be tested every 3 years when extinguisher maintenance is performed.<br>2.5. A written log of required hydrostatic test dates for extinguishers shall be maintained by the owner to verify that hydrostatic tests are conducted at the frequency required by NFPA 10.<br>3. In Group I-3, portable fire extinguishers shall be permitted to be located at staff locations.<br><br>(IFC 906.2 2021) | Corrected |

**15 Unobstructed and Unobscured**

| | |
|---|---|
| Portable fire extinguishers shall not be obstructed or obscured from view. In rooms or areas in which visual obstruction cannot be completely avoided, means shall be provided to indicate the locations of extinguishers.<br><br>(IFC 906.6 2021) | Corrected |

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____

| | | | |
|---|---|---|---|
| ***Business Name*** | Murano Senior Living | ***Provider Number*** | 2521 |
| ***Address*** | 620 TERRY AVE , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Seattle, WA 98104 | ***Facility Type*** | Residential Care |

On 03/23/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|
| **16 Hangers and Brackets** | |
| Hand-held portable fire extinguishers, not housed in cabinets, shall be installed on the hangers or brackets supplied. Hangers or brackets shall be securely anchored to the mounting surface in accordance with the manufacturer's installation instructions.<br><br>(IFC 906.7 2021) | Findings during the inspection were:<br><br>Portable fire extinguisher in the Bistro kitchen is not securely anchored. |
| **17 Smoke Detector Sensitivity** | |
| Smoke detector sensitivity shall be checked within one year after installation and every alternate year thereafter. After the second calibration test, where sensitivity tests indicate that the detector has remained within its listed and marked sensitivity range (or 4-percent obscuration light grey smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. Where the frequency is extended, records of detector-caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or areas where nuisance alarms show any increase over the previous year, calibration tests shall be performed.<br><br>(IFC 907.8.3 2021) | Findings during the inspection were:<br><br>No documentation was provided for the sensitivity test of the fire alarm system.<br>*All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.* |

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____

| | | | |
|---|---|---|---|
| ***Business Name*** | Murano Senior Living | ***Provider Number*** | 2521 |
| ***Address*** | 620 TERRY AVE , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Seattle, WA 98104 | ***Facility Type*** | Residential Care |

On 03/23/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|

**18 Fuel-Burn Appliances Outside of Dwelling, Sleep Units & Classro**

| | |
|---|---|
| Carbon monoxide detection shall be provided in dwelling units, sleeping units and classrooms located in buildings that contain fuel-burning appliances or fuel-burning fireplaces.<br><br>Exceptions:<br>1. Carbon monoxide detection shall not be required in dwelling units, sleeping units and classrooms without communicating openings between the fuel-burning appliance or fuel-burning fireplace and the dwelling unit, sleeping unit or classroom.<br>2. Carbon monoxide detection shall not be required in dwelling units, sleeping units and classrooms where a carbon monoxide detector is provided in one of the following locations:<br>2.1. In an approved location between the fuel-burning appliance or fuel-burning fireplace and the dwelling unit, sleeping unit or classroom.<br>2.2. On the ceiling of the room containing the fuel-burning appliance or fuel-burning fireplace.<br><br>(IFC 915.1.4 2021) | Corrected |

**19 Rooms and Spaces**

| | |
|---|---|
| In the event of power supply failure, and emergency electrical system shall automatically illuminate all of the following areas:<br><br>1. Electrical equipment rooms.<br>2. Fire command centers.<br>3. Fire Pump rooms<br>4. Generator rooms<br>5. Public restrooms with an area greater than 300 square feet (27.87 m2).<br><br>(IFC 1008.3.3 2021) | Corrected |

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____

| | | | |
|---|---|---|---|
| ***Business Name*** | Murano Senior Living | ***Provider Number*** | 2521 |
| ***Address*** | 620 TERRY AVE , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Seattle, WA 98104 | ***Facility Type*** | Residential Care |

On 03/23/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|
| **20 Reliability** | |
| Required exit accesses, exits and exit discharges shall be continuously maintained free from obstructions or impediments to full instant use in the case of fire or other emergency when the building area served by the means of egress is occupied. An exit or exit passageway shall not be used for any purpose that interferes with a means of egress.<br><br>(IFC 1032.2 2021) | Corrected |
| **21 Maintenance** | |
| Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required.<br><br>(IFC 1203.4 2021) | Corrected |
| **22 Securing Compressed Gas Containers, Cylinders and Tanks** | |
| Compressed gas containers, cylinders and tanks shall be secured to prevent falling caused by contact, vibration or seismic activity. Securing of compressed gas containers, cylinders and tanks shall be by one of the following methods:<br><br>1. Securing containers, cylinders and tanks to a fixed object with one or more restraints.<br>2. Securing containers, cylinders and tanks on a cart or other mobile device designed for the movement of compressed gas containers, cylinders or tanks.<br>3. Nesting of compressed gas containers, cylinders and tanks at container filling or servicing facilities or in sellers' warehouses not open to the public. Nesting shall be allowed provided that the nested containers, cylinders or tanks, if dislodged, do not obstruct the required means of egress.<br>4. Securing of compressed gas containers, cylinders and tanks to or within a rack, framework, cabinet or similar assembly designed for such use.<br><br>Exception: Compressed gas containers, cylinders and tanks in process of examination, filling, transport or servicing.<br><br>(IFC 5303.5.3 2021) | Corrected |

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____

**Washington State Patrol**
**Fire Protection Bureau**
Phone: (360) 596-3900

| | | | |
|---|---|---|---|
| ***Business Name*** | Murano Senior Living | ***Provider Number*** | 2521 |
| ***Address*** | 620 TERRY AVE , | ***Approval Status*** | Disapproved |
| ***City, State, Zip*** | Seattle, WA 98104 | ***Facility Type*** | Residential Care |

On 03/23/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

| Code Requirement | Statement of Violation |
|---|---|

**Next inspection scheduled on or after: 04/22/2026**

**Right of appeal.** Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

*Signature*

Marshall Nisbet Plant Ops Director
Print Name and Title

Deputy State Fire Marshal Alan Harlan
2803 156TH AVE SE
Bellevue WA 98007
(425) 495-7121

Alan Harlan Digitally signed by Alan Harlan Date: 2026.03.24 16:12:11 -07'00'

*Signature*

This document was prepared by Residential Care Services for the Locator website.



Initials of Authorized Facility Representative: _____