Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Merrill Gardens at Tukwila	***Provider Number***	2727
Address	112 ANDOVER PARK E,	***Approval Status***	Approved
City, State, Zip	Tukwila, WA 98188	***Facility Type***	Residential Care

On 09/02/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative

_____ Shane Fowler, GM
Signature *Print Name and Title*

Deputy State Fire Marshal Cozetta Christian
106 11th AVE SW
Olympia WA 98501
(360) 584-5796

_____
Signature

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Initials of Authorized Facility Representative:_____

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Merrill Gardens at Tukwila	***Provider Number***	2727
Address	112 ANDOVER PARK E,	***Approval Status***	Disapproved
City, State, Zip	Tukwila, WA 98188	***Facility Type***	Residential Care

On 08/25/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation

1 Admin Fire & Life Safety Inspection

2 Storage in buildings.

Storage of materials in buildings shall be orderly and stacks shall be stable. Storage of combustible materials shall be separated from heaters or heating devices by distance or shielding so that ignition cannot occur. (IFC 315.3 2021)	

3 Appliance Connection to Building Piping

Gas-fired commercial cooking appliances installed on casters and appliances that are moved for cleaning and sanitation purposes shall be connected to the piping system with an appliance connector listed as complying with ANSI Z21.69/CSA 6.16. The commercial cooking appliance connector installation shall be configured in accordance with the manufacturer's installation instructions. Movement of appliances with casters shall be limited by a restraining device installed in accordance with the connector and appliance manufacturer's instructions. (IFC 606.4 2021)	

4 Owner's Responsibility

The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space. (IFC 701.6 2021)	The following violations were observed: Facility was unable to provide documentation for their annual fire rated construction inspection.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Merrill Gardens at Tukwila	***Provider Number***	2727
Address	112 ANDOVER PARK E,	***Approval Status***	Disapproved
City, State, Zip	Tukwila, WA 98188	***Facility Type***	Residential Care

On 08/25/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
5 Inspection and Maintenance	
Opening protectives in fire-resistance-rated assemblies shall be inspected and maintained in accordance with NFPA 80. Opening protectives in smoke barriers shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Openings in smoke partitions shall be inspected and maintained in accordance with NFPA 105. Fire doors and smoke and draft control doors shall not be blocked, obstructed, or otherwise made inoperable. Fusible links shall be replaced promptly whenever fused or damaged. Opening protectives and smoke and draft control doors shall not be modified. (IFC 705.2 2021) 5.2.1 Inspection and Testing. Upon completion of the installation, door, shutters, and window assemblies shall be inspected and tested in accordance with 5.2.4. 5.2.4 Periodic Inspection and Testing. 5.2.4.1 Periodic inspections and testing shall be performed not less than annually. 5.2.2.4 A record of all inspections and testing shall be provided that includes, but is not limited to, the following information: 1. Date of inspection 2. Name of facility 3. Address of facility 4. Name of person(s) performing inspections and testing 5. Company name and address of inspecting company 6. Signature of inspector of record 7. Individual record of each inspected and tested fire door assembly 8. Opening identifier and location of each inspected and tested fire door assembly 9. Type and description of each inspected and tested fire door assembly To aid the AHJ during the review of the inspections and testing reports, the records should include a description of the type of fire door assembly as follows: Type 6: Swinging door with builders hardware Type 7: Swinging fire door with fire door hardware Type 8: Horizontally sliding fire door Type 9: Special purpose horizontally accordion or folding	

Initials of Authorized Facility Representative: _____

This document was prepared by Residential Care Services for the Locator website.

Business Name	Merrill Gardens at Tukwila	***Provider Number***	2727
Address	112 ANDOVER PARK E,	***Approval Status***	Disapproved
City, State, Zip	Tukwila, WA 98188	***Facility Type***	Residential Care

On 08/25/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
door Type 10: Vertically sliding fire door Type 11: Rolling steel door Type 12: Fire shutter Type 13: Service counter fire door Type 14: Hoistway doors for elevators and dumbwaiter Type 15: Chute door Type 16: Access door Type 17: Fire window 10. Verification of visual inspection and functional operation 11. Listing of deficiencies in accordance with 5.2.3, Section 5.3, and Section 5.4 As a minimum, the following items shall be verified: 1. Labels are clearly visible and legible. 2. No open holes or breaks exist in surfaces of either the door or frame. 3. Glazing, vision light frames, and glazing beads are intact and securely fastened in place, if so equipped. 4. The door, frame, hinges, hardware, and noncombustible threshold are secured, aligned and in working order with no visible signs of damage. 5. No parts are missing or broken. 6. Door clearances do not exceed clearances listed in 4.8.4 and 6.3.1.7 7. The self-closing device is operational; that is, the active door completely closes when operated from the full open position. 8. If a coordinator is installed, the inactive leaf closes before the active leaf. 9. Latching hardware operates and secures the door when it is in the closed position. 10. Auxiliary hardware items that interfere or prohibit operation are not installed on the door or frame. 11. No field modifications to the door assembly have been performed that void the label. 12. Meeting edge protection, gasketing and edge seals where required, are inspected to verify their presence and integrity. 13. Signage affixed to a door meets the requirements listed in 4.1.4 (NFPA 80.5.2)	

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Merrill Gardens at Tukwila	***Provider Number***	2727
Address	112 ANDOVER PARK E,	***Approval Status***	Disapproved
City, State, Zip	Tukwila, WA 98188	***Facility Type***	Residential Care

On 08/25/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
6 Duct and Air Transfer Openings - Maintaining Protection	
Dampers protecting ducts and air transfer openings shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Other products or materials used to protect the openings for ducts and air transfer openings shall be securely attached to or bonded to the construction containing the duct or air transfer opening, without visible openings through or into the cavity of the construction. Any damaged products or materials protecting duct and air transfer openings shall be repaired, restored or replaced. (IFC 706.1 2018)	
7 Testing and Maintenance	
Sprinkler systems shall be tested and maintained in accordance with Section 901. (IFC 903.5 2021)	
8 Inspection, Testing and Maintenance	
The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained. (IFC 907.8 2021)	
9 Carbon Monoxide Detection - General	
Carbon monoxide detection shall be installed in new buildings in accordance with Sections 915.1.1 through 915.6. Carbon monoxide detection shall be installed in existing buildings in accordance with Chapter 11 of the International Fire Code. (IFC 0915.1 2021 WAC 51-54A)	

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Merrill Gardens at Tukwila	***Provider Number***	2727
Address	112 ANDOVER PARK E,	***Approval Status***	Disapproved
City, State, Zip	Tukwila, WA 98188	***Facility Type***	Residential Care

On 08/25/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
10 Rooms and Spaces	
In the event of power supply failure, and emergency electrical system shall automatically illuminate all of the following areas: 1. Electrical equipment rooms. 2. Fire command centers. 3. Fire Pump rooms 4. Generator rooms 5. Public restrooms with an area greater than 300 square feet (27.87 m2). (IFC 1008.3.3 2021)	
11 Maintenance	
Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required. (IFC 1203.4 2021)	

Next inspection scheduled on or after: 09/24/2026

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Jason Davis

Signature

Jason Davis Maintenance Director

Print Name and Title

Deputy State Fire Marshal Larisa Hennessy
2803 156TH AVE SE
Bellevue WA 98007
(425) 620-5012

Signature

Initials of Authorized Facility Representative: _____

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Merrill Gardens at Tukwila	***Provider Number***	2727
Address	112 ANDOVER PARK E,	***Approval Status***	Disapproved
City, State, Zip	Tukwila, WA 98188	***Facility Type***	Residential Care

On 06/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation

1 Admin Fire & Life Safety Inspection

	This report is the result of an unannounced fire and life safety re-certification survey conducted at Merrill Gardens at Tukwila on 6/24/2026 by a DSFM representative of the Washington State Patrol, Fire Protection Bureau to determine compliance with all applicable codes. All inspection reports must be completely filled out from the vendor and verify the report shows no deficiencies. If deficiencies are noted on report, additional documentation will be required to show that deficiencies have been corrected prior to re-inspection. The facility is not in compliance at the time of this inspection.

2 Storage in buildings.

Storage of materials in buildings shall be orderly and stacks shall be stable. Storage of combustible materials shall be separated from heaters or heating devices by distance or shielding so that ignition cannot occur. (IFC 315.3 2021)	The following deficiencies were cited as a result of this inspection: At time of inspection the following was observed: 1. On the 5th floor there is Combustible materials with 18 inches of the sprinkler.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Merrill Gardens at Tukwila	***Provider Number***	2727
Address	112 ANDOVER PARK E,	***Approval Status***	Disapproved
City, State, Zip	Tukwila, WA 98188	***Facility Type***	Residential Care

On 06/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
3 Appliance Connection to Building Piping	
Gas-fired commercial cooking appliances installed on casters and appliances that are moved for cleaning and sanitation purposes shall be connected to the piping system with an appliance connector listed as complying with ANSI Z21.69/CSA 6.16. The commercial cooking appliance connector installation shall be configured in accordance with the manufacturer's installation instructions. Movement of appliances with casters shall be limited by a restraining device installed in accordance with the connector and appliance manufacturer's instructions. (IFC 606.4 2021)	The following deficiencies were cited as a result of this inspection: At time of inspection the following was observed: 1. In the kitchen there is appliance not connect to the wall with required restraint.
4 Owner's Responsibility	
The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space. (IFC 701.6 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following documentation was not provided. 1. The facility must maintain detailed documentation and maps of fire-rated construction locations, including annual inspection reports detailing testing dates, modifications, and repairs.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Merrill Gardens at Tukwila	***Provider Number***	2727
Address	112 ANDOVER PARK E,	***Approval Status***	Disapproved
City, State, Zip	Tukwila, WA 98188	***Facility Type***	Residential Care

On 06/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
5 Inspection and Maintenance	
Opening protectives in fire-resistance-rated assemblies shall be inspected and maintained in accordance with NFPA 80. Opening protectives in smoke barriers shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Openings in smoke partitions shall be inspected and maintained in accordance with NFPA 105. Fire doors and smoke and draft control doors shall not be blocked, obstructed, or otherwise made inoperable. Fusible links shall be replaced promptly whenever fused or damaged. Opening protectives and smoke and draft control doors shall not be modified. (IFC 705.2 2021) 5.2.1 Inspection and Testing. Upon completion of the installation, door, shutters, and window assemblies shall be inspected and tested in accordance with 5.2.4. 5.2.4 Periodic Inspection and Testing. 5.2.4.1 Periodic inspections and testing shall be performed not less than annually. 5.2.2.4 A record of all inspections and testing shall be provided that includes, but is not limited to, the following information: 1. Date of inspection 2. Name of facility 3. Address of facility 4. Name of person(s) performing inspections and testing 5. Company name and address of inspecting company 6. Signature of inspector of record 7. Individual record of each inspected and tested fire door assembly 8. Opening identifier and location of each inspected and tested fire door assembly 9. Type and description of each inspected and tested fire door assembly To aid the AHJ during the review of the inspections and testing reports, the records should include a description of the type of fire door assembly as follows: Type 6: Swinging door with builders hardware Type 7: Swinging fire door with fire door hardware Type 8: Horizontally sliding fire door Type 9: Special purpose horizontally accordion or folding	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following documentation was not provided. 1. The report did not show all fire rated doors, including resident doors.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Merrill Gardens at Tukwila	***Provider Number***	2727
Address	112 ANDOVER PARK E,	***Approval Status***	Disapproved
City, State, Zip	Tukwila, WA 98188	***Facility Type***	Residential Care

On 06/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
door Type 10: Vertically sliding fire door Type 11: Rolling steel door Type 12: Fire shutter Type 13: Service counter fire door Type 14: Hoistway doors for elevators and dumbwaiter Type 15: Chute door Type 16: Access door Type 17: Fire window 10. Verification of visual inspection and functional operation 11. Listing of deficiencies in accordance with 5.2.3, Section 5.3, and Section 5.4 As a minimum, the following items shall be verified: 1. Labels are clearly visible and legible. 2. No open holes or breaks exist in surfaces of either the door or frame. 3. Glazing, vision light frames, and glazing beads are intact and securely fastened in place, if so equipped. 4. The door, frame, hinges, hardware, and noncombustible threshold are secured, aligned and in working order with no visible signs of damage. 5. No parts are missing or broken. 6. Door clearances do not exceed clearances listed in 4.8.4 and 6.3.1.7 7. The self-closing device is operational; that is, the active door completely closes when operated from the full open position. 8. If a coordinator is installed, the inactive leaf closes before the active leaf. 9. Latching hardware operates and secures the door when it is in the closed position. 10. Auxiliary hardware items that interfere or prohibit operation are not installed on the door or frame. 11. No field modifications to the door assembly have been performed that void the label. 12. Meeting edge protection, gasketing and edge seals where required, are inspected to verify their presence and integrity. 13. Signage affixed to a door meets the requirements listed in 4.1.4 (NFPA 80.5.2)	

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Merrill Gardens at Tukwila	***Provider Number***	2727
Address	112 ANDOVER PARK E,	***Approval Status***	Disapproved
City, State, Zip	Tukwila, WA 98188	***Facility Type***	Residential Care

On 06/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
6 Duct and Air Transfer Openings - Maintaining Protection	
Dampers protecting ducts and air transfer openings shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Other products or materials used to protect the openings for ducts and air transfer openings shall be securely attached to or bonded to the construction containing the duct or air transfer opening, without visible openings through or into the cavity of the construction. Any damaged products or materials protecting duct and air transfer openings shall be repaired, restored or replaced. (IFC 706.1 2018)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following documentation was not provided. 1. The facility could only show the repair report for the dampers, not the original report and when it was performed.
7 Testing and Maintenance	
Sprinkler systems shall be tested and maintained in accordance with Section 901. (IFC 903.5 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following documentation was not provided. 1. Annual forward flow test (NFPA 25 13.7.2.1) 2. Semi-Annual Report 3. The annual report from 6/12/2025 shows decencies that the facility could not show that they have been resolved.
8 Inspection, Testing and Maintenance	
The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained. (IFC 907.8 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following documentation was not provided. 1. The annual report from 6/12/2025 shows decencies that the facility could not show that they have been resolved.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Business Name	Merrill Gardens at Tukwila	***Provider Number***	2727
Address	112 ANDOVER PARK E,	***Approval Status***	Disapproved
City, State, Zip	Tukwila, WA 98188	***Facility Type***	Residential Care

On 06/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
9 Carbon Monoxide Detection - General	
Carbon monoxide detection shall be installed in new buildings in accordance with Sections 915.1.1 through 915.6. Carbon monoxide detection shall be installed in existing buildings in accordance with Chapter 11 of the International Fire Code. (IFC 0915.1 2021 WAC 51-54A)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following documentation was not provided. 1. The facility must maintain detailed documentation of carbon monoxide detector locations, including monthly inspection reports detailing testing dates, modifications, and repairs.
10 Rooms and Spaces	
In the event of power supply failure, and emergency electrical system shall automatically illuminate all of the following areas: 1. Electrical equipment rooms. 2. Fire command centers. 3. Fire Pump rooms 4. Generator rooms 5. Public restrooms with an area greater than 300 square feet (27.87 m2). (IFC 1008.3.3 2021)	The following deficiencies were cited as a result of this inspection: At time of inspection the following was observed: 1. Emergency lighting with battery is needed in sprinkler riser room.
11 Maintenance	
Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required. (IFC 1203.4 2021)	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following documentation was not provided. 1. Diesel fuel testing report

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Merrill Gardens at Tukwila	***Provider Number***	2727
Address	112 ANDOVER PARK E,	***Approval Status***	Disapproved
City, State, Zip	Tukwila, WA 98188	***Facility Type***	Residential Care

On 06/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation

Next inspection scheduled on or after: 07/24/2026

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

_____ _____
Signature *Print Name and Title*

Deputy State Fire Marshal Jason Van Gorkum
2502 112 ST E
Tacoma WA 984455104
(509) 406-7209

_____
Signature

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____