Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Cashemre assisted living	***Provider Number***	2773
Address	809 PIONEER ,	***Approval Status***	Approved
City, State, Zip	Cashmere, WA 98815	***Facility Type***	Residential Care

On 09/01/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
1 Relocatable power taps and current taps	
Relocatable power taps and current taps. The construction and use of current taps and relocatable power taps shall be in accordance with NFPA 70 and this code. (IFC 603.5, 2021)	The following violation was observed: -In Room 114 there was an unfused multiplug adapter in use in the bathroom. *CORRECTED*
2 Owner's Responsibility	
The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space. (IFC 701.6 2021)	The following violations were observed: -The facility failed to provide documentation of the annual fire-resistance-rated construction inspection completed within the past twelve months. *CORRECTED* -There was a penetration in the ceiling tile outside of the Riser Room on the 1st floor. *CORRECTED*
3 Inspection and Maintenance	
Opening protectives in fire-resistance-rated assemblies shall be inspected and maintained in accordance with NFPA 80. Opening protectives in smoke barriers shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Openings in smoke partitions shall be inspected and maintained in accordance with NFPA 105. Fire doors and smoke and draft control doors shall not be blocked, obstructed, or otherwise made inoperable. Fusible links shall be replaced promptly whenever fused or damaged. Opening protectives and smoke and draft control doors shall not be modified. (IFC 705.2 2021)	The following violation was observed: -The second floor elevator fire door failed to fully close and latch upon testing. *CORRECTED*

Initials of Authorized Facility Representative: HH

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Cashemre assisted living	***Provider Number***	2773
Address	809 PIONEER ,	***Approval Status***	Approved
City, State, Zip	Cashmere, WA 98815	***Facility Type***	Residential Care

On 09/01/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
4 Systems Out of Service	
Where a required fire protection system is out of service, the fire department and the fire code official shall be notified immediately and, where required by the fire code official, the building shall either be evacuated or an approved fire watch shall be provided for all occupants left unprotected by the shut down until the fire protection system has been returned to service. Where utilized, fire watches shall be provided with at least one approved means for notification of the fire department and their only duty shall be to perform constant patrols of the protected premises and keep watch for fires. Exception: Facilities with an approved notification and impairment management program. The notification and impairment program for water-based fire protection systems shall comply with NFPA 25. (IFC 901.7 2021)	The following violation was observed: The Fire Alarm annunciator located on the first floor was showing the following trouble signal alarm upon inspection at approximately 1100 hours: -"Troubl RELAY (1FC), INVREF, 1105A 071826 1M088" Staff were directed to contact their licensor and local Fire Department to report the system outage, and a Fire Watch for the affected areas was required at 1100 hours on July 20, 2026 for 15-minute increments. Documentation of fire watch logs and service report repairs shall be submitted to our office for review to be released from fire watch duties. *CORRECTED*
5 Inspection, Testing and Maintenance	
The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained. (IFC 907.8 2021)	The following violations were observed: -The facility was unable to provide documentation of the semi-annual inspection, testing, and maintenance of the fire alarm system within the past twelve months. *CORRECTED* -The facility was unable to provide documentation of the monthly smoke alarm testing for the months of March through June of 2026. *CORRECTED*

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: HH

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Cashemre assisted living	***Provider Number***	2773
Address	809 PIONEER ,	***Approval Status***	Approved
City, State, Zip	Cashmere, WA 98815	***Facility Type***	Residential Care

On 09/01/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
6 Carbon Monoxide Detection - General	
Carbon monoxide detection shall be installed in new buildings in accordance with Sections 915.1.1 through 915.6. Carbon monoxide detection shall be installed in existing buildings in accordance with Chapter 11 of the International Fire Code. (IFC 0915.1 2021 WAC 51-54A)	The following violation was observed: -The facility failed to provide documentation of the monthly carbon monoxide testing for the months of March through June 2026 within the past twelve months. *CORRECTED*

Next inspection scheduled on or after: 07/31/2027

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Nate Orange Maintenance Director
Print Name and Title

Deputy State Fire Marshal Andrea Ely
2715 RUDKIN RD
Union Gap WA
(509) 531-3384

Andrea Ely
Signature

Digitally signed by Andrea Ely
Date: 2026.09.01 11:07:21 -07'00'
Adobe Acrobat Reader version: 2026.001.21789

Initials of Authorized Facility Representative: HH

This document was prepared by Residential Care Services for the Locator website.