Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Laurel Place	***Provider Number***	2781
Address	1133 E PARK AVE ,	***Approval Status***	Approved
City, State, Zip	Port Angeles, WA 98362	***Facility Type***	Residential Care

On 08/18/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative

Signature

Holly Jangula P.OA.

Print Name and Title

Deputy State Fire Marshal Raul Murcia
PO BOX 42642
Olympia WA 98504
(360) 819-0067

Signature

This document was prepared by Residential Care Services for the Locator website.

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Laurel Place	***Provider Number***	2781
Address	1133 E PARK AVE ,	***Approval Status***	Disapproved
City, State, Zip	Port Angeles, WA 98362	***Facility Type***	Residential Care

On 06/30/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation

1 Abatement of Electrical Hazards

Abatement of unsafe conditions and electrical hazards. Conditions that constitute an electrical shock or fire hazard shall be abated.. (IFC 603.2 2021)	Findings during the inspection were: Facility failed to maintain electrical outlet in Salon room, broken outlet on left of room.

2 Extension Cords

Extension cords. Extension cords shall not be a substitute for permanent wiring and shall be listed and labeled in accordance with UL 817. Extension cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances. Extension cords marked for indoor use shall not be used outdoors.. (IFC 603.6 2021)	Corrected.

3 Owner's Responsibility

The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space. (IFC 701.6 2021)	Corrected.

Initials of Authorized Facility Representative:_____

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Laurel Place	***Provider Number***	2781
Address	1133 E PARK AVE ,	***Approval Status***	Disapproved
City, State, Zip	Port Angeles, WA 98362	***Facility Type***	Residential Care

On 06/30/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
4 Testing and Maintenance	
Sprinkler systems shall be tested and maintained in accordance with Section 901. (IFC 903.5 2021)	Corrected.
5 Operations and Mainenance	
Automatic fire-extinguishing systems protecting commercial cooking systems shall be maintained in accordance with Sections 904.13.5.1 through 904.13.5.3. (IFC 904.13.5 2021)	Findings during the inspection were: Kitchen suppression system report from Amerisafe conducted on 5/7/2025 states deficiencies with kitchen fan. Deficiencies shall be corrected.
6 Inspection, Testing and Maintenance	
The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained. (IFC 907.8 2021)	Findings during the inspection were: Facility failed to provide documentation showing smoke alarms are being inspected monthly.
7 Smoke Detector Sensitivity	
Smoke detector sensitivity shall be checked within one year after installation and every alternate year thereafter. After the second calibration test, where sensitivity tests indicate that the detector has remained within its listed and marked sensitivity range (or 4-percent obscuration light grey smoke, if not marked), the length of time between calibration tests shall be permitted to be extended to a maximum of 5 years. Where the frequency is extended, records of detector-caused nuisance alarms and subsequent trends of these alarms shall be maintained. In zones or areas where nuisance alarms show any increase over the previous year, calibration tests shall be performed. (IFC 907.8.3 2021)	Findings during the inspection were: Facility failed to provide 5 year smoke detectors sensitivity test.
8 Emergnecy Lighting Equipment Inspection and Testing	
Emergency lighting shall be maintained in accordance with Section 1008 and shall be inspected and tested in accordance with Sections 1031.10.1 and 1031.10.2. (IFC 1032.10 2021)	Corrected.

Initials of Authorized Facility Representative:_____

This document was prepared by Residential Care Services for the Locator website.

Business Name	Laurel Place	***Provider Number***	2781
Address	1133 E PARK AVE ,	***Approval Status***	Disapproved
City, State, Zip	Port Angeles, WA 98362	***Facility Type***	Residential Care

On 06/30/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
9 Activation Test	
Emergency lighting equipment shall be tested monthly for a duration of not less than 30 seconds. The test shall be performed manually or by an automated self-testing and self-diagnostic routine. Where testing is performed by self-testing and self-diagnostics, a visual inspection of the emergency lighting equipment shall be conducted monthly to identify any equipment displaying a trouble indicator or that has become damaged or otherwise impaired. (IFC 1032.10.1 2021)	Corrected.
10 Power Test	
Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes. (IFC 1031.10.2 2021)	Findings during the inspection were: Facility failed to provide annual 1.5 hour test for exit signs and emergency lights.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative:_____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Laurel Place	***Provider Number***	2781
Address	1133 E PARK AVE ,	***Approval Status***	Disapproved
City, State, Zip	Port Angeles, WA 98362	***Facility Type***	Residential Care

On 06/30/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
11 NFPA 80 Fire Door Inspection and Testing	
5.2.1 Inspection and Testing. Upon completin of the installation, door, shutters, and window assemblies shall be inspected and tested in accordance with 5.2.4. 5.2.4 Periodic Inspection and Testing. 5.2.4.1 Periodic inspections and testing shall be performed not less than annually. 5.2.2.4 A record of all inspections and testing shall be provided that includes, but is not limited to, the following information: 1. Date of inspection 2. Name of facility 3. Address of facility 4. Name of person(s) performing inspections and testing 5. Company name and address of inspecting company 6. Signature of inspector of record 7. Individual record of each inspected and tested fire door assembly 8. Opening identifier and location of each inspected and tested fire door assembly 9. Type and description of each inspected and tested fire door assembly 10. Verification of visual inspection and functional operation 11. Listing of deficiencies in accordance with 5.2.3, Section 5.3, and Section 5.4 And the following hall be checked: 1. Labels are clearly visible and legible 2. No open holes or breaks exist in surfaces of wither the door or frame 3. Glazing, vision light frames, and glazing beads are intact and securely fastened in place, if so equipped. 4. The door, frame, hinges, hardware, and non combustible threshold are secured, aligned and in working order with no visible, signs of damage 5. No parts are missing or broken 6. Door clearances do not exceed clearances listed in 4.8.4 and 6.3.1.7 7. The self-closing device is operational,: that is, the active door completely closes when operated from the full open position 8. If a coordinator is installed, the inactive lead close before the active lead	Findings during the inspection were: Facility failed to the following doors; -Double doors by resident laundry in Hall 100, failed to latch.

Initials of Authorized Facility Representative:_____

This document was prepared by Residential Care Services for the Locator website.

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Laurel Place	***Provider Number***	2781
Address	1133 E PARK AVE ,	***Approval Status***	Disapproved
City, State, Zip	Port Angeles, WA 98362	***Facility Type***	Residential Care

On 06/30/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
9. Latching hardware operates and secures the door when it is in the closed positon 10. Auxiliary hardware items that interfere or prohibit operation are not installed on the door or frame 11. No field modification to the door assembly have been preformed that void the label. 12. Meeting edge protection, gasketing and edge seals where required, are inspected to verify their presence and intertie 13. Signage affixed to a door meets the requirements listed in 4.1.4	

Next inspection scheduled on or after: 07/31/2026

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Holly Jangula
Signature

Holly Jangula Administrator
Print Name and Title

Deputy State Fire Marshal Raul Murcia
PO BOX 42642
Olympia WA 98504
(360) 819-0067

Signature

Initials of Authorized Facility Representative:_____

This document was prepared by Residential Care Services for the Locator website.