Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Josephine Caring Community (BH)	***Provider Number***	000569
Address	9901 272 ND ,	***Approval Status***	Approved
City, State, Zip	Stanwood, WA 98292	***Facility Type***	Residential Care

On 08/24/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative

Signature

Alyna Madley Recept.
Print Name and Title

Deputy State Fire Marshal Brandon G. Brown
MP 235 SB Interstate 5
Bow WA 98232
(360) 791-7037

Signature

This document was prepared by Residential Care Services for the Locator website.

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Josephine Caring Community (BH)	***Provider Number***	000569
Address	9901 272 ND ,	***Approval Status***	Disapproved
City, State, Zip	Stanwood, WA 98292	***Facility Type***	Residential Care

On 07/15/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation

1 Inspection and Maintenance

Opening protectives in fire-resistance-rated assemblies shall be inspected and maintained in accordance with NFPA 80. Opening protectives in smoke barriers shall be inspected and maintained in accordance with NFPA 80 and NFPA 105. Openings in smoke partitions shall be inspected and maintained in accordance with NFPA 105. Fire doors and smoke and draft control doors shall not be blocked, obstructed, or otherwise made inoperable. Fusible links shall be replaced promptly whenever fused or damaged. Opening protectives and smoke and draft control doors shall not be modified. (IFC 705.2 2021)	1. Resident room 202 fire rated door that opens to the corridor was blocked open by a chair, preventing it from closing and latching. 2. Resident room 118 fire rated door that opens to the corridor was blocked open by a trashcan, preventing it from closing and latching.

2 Door Operation

Swinging fire doors shall close from the full-open position and latch automatically. (IFC 705.2.4 2021)	1. Resident room 271 fire door would not close and latch from the fully open position. 2. The fire rated cross corridor door near room 314 would not close and latch from the fully open position.

3 Internally Illuminated Exit Signs

Electrically powered, self-luminous and photoluminescent exit signs shall be listed and labeled in accordance with UL 924 and shall be installed in accordance with the manufacturer's instructions and Section 1203. Exit signs shall be illuminated at all times. (IFC 1013.5 2021)	The internally illuminated exit signs near the elevator room would not illuminate when the activation test button was pushed.

This document was prepared by Residential Care Services for the Locator website.

Initials of Authorized Facility Representative: _____

Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Josephine Caring Community (BH)	***Provider Number***	000569
Address	9901 272 ND ,	***Approval Status***	Disapproved
City, State, Zip	Stanwood, WA 98292	***Facility Type***	Residential Care

On 07/15/2026 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation

Next inspection scheduled on or after: 08/14/2026

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

CLINT BURCHARD DFEO
Print Name and Title

Deputy State Fire Marshal Brandon G. Brown
MP 235 SB Interstate 5
Bow WA 98232
(360) 791-7037

Brandon Brown Digitally signed by Brandon Brown Date: 2026.07.16 06:20:54 -07'00'
Signature

Initials of Authorized Facility Representative: _____

This document was prepared by Residential Care Services for the Locator website.