

**AGENCY FOR HEALTH CARE
ADMINISTRATION**

PRINTED: 11/13/2018
FORM APPROVED

STATEMENT OF DEFICIENCIES	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: AL11965273	(X3) DATE SURVEY COMPLETED R 10/29/2018
NAME OF PROVIDER OR SUPPLIER HARBOR INN OF VENICE SOUTH	STREET ADDRESS, CITY, STATE, ZIP CODE 160 RUTLAND ROAD VENICE, FL 34293	
SUMMARY STATEMENT OF DEFICIENCIES (FINDINGS PRECEDED BY TAGS AND REGULATORY IDENTIFYING INFORMATION)		
0000 - Initial Comments An unannounced revisit survey was conducted on _____ at Harbor Inn of Venice South, an assisted living facility (license number #9691) in Venice, Florida. This was a follow-up to the emergency power plan monitoring survey completed on _____. The following is description of the deficiency found at the time of the visit. 0200 - Emergency Environmental Control - 58A-5.036 FAC Based on observation, record review, and interview, the facility failed to ensure there was sufficient gasoline containers to store 96 hours of fuel and the gasoline storage box was not safe for storage. The lack of safe storage and insufficient storage containers can place the residents at risk for a gasoline explosion or risk of insufficient temperatures after an emergency. The findings included: On _____ at 10:15 a.m., observation of the emergency supply of gasoline the facility had stored in the facility revealed the facility had ten 5 gallon jugs of gasoline as their supply for a total of 50 gallons of gas. The gasoline was stored in a wooden box behind a shed. When the box was opened, there was a strong odor of gasoline noted from the stored jugs of gasoline. This box was flammable and would not meet the National Fire Protection Association and Occupational Safety and Health Administration regulations to store gasoline. A review of the facility's Emergency Power Plan, approved by the county on _____ and implemented by the facility on _____, showed the requirement for the generator for 96 hours of use would be 90 gallons of gas. The facility had 50 gallons to meet the 48 hour storage requirement, but lacked the additional 8, 5 gallon cans to obtain the rest of the gas once an emergency was declared. On _____ at 10:30 a.m., the Assistant Administrator agreed she did not have sufficient gas for the generator to work for the required 96 hours. Class III		