

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL012033	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 03/06/2018
NAME OF PROVIDER OR SUPPLIER EAST VIEW FAMILY CARE		STREET ADDRESS, CITY, STATE, ZIP CODE 3208 TEX'S FISHCAMP ROAD CONNELLY SPG, NC 28612		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report by Greg Williams DHSR Construction Section conducted a Biennial Survey on March 6, 2018 from 11:00 AM to 12:15 PM at the above referenced facility. DHSR records indicate the home was first licensed on January 10, 1986 as a Family Care Home for six (6) ambulatory Residents (who are able to respond and evacuate without physical or verbal assistance during a fire or other emergency). Based on this we are requiring the home to be in compliance with the following: The 1984 Minimum Standards and Regulations for Family Care Homes, the applicable portions of the 2005 Rules for Family Care Homes 10A NCAC 13G, and the 1978 (Rev 10) North Carolina State Building Code - Section 409.1(g) - Residential Care Homes At the time of our visit, we cited deficiencies that require an acceptable plan of correction. They are as follows:	C 000		
C 148	Outside Entrances/Exits-Free of Obstructions SECTION .0300 - THE BUILDING 10A NCAC 13G .0312 OUTSIDE ENTRANCE AND EXITS (e) All entrances/exits shall be free of all obstructions or impediments to allow for full instant use in case of fire or other emergency. This Rule is not met as evidenced by: 1. At the time of the survey it was observed that there was a chain latch lock on the Staff Bedroom door. This rule requires all entrances/exits be free of obstructions in the case of an emergency.	C 148		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL012033	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 03/06/2018
NAME OF PROVIDER OR SUPPLIER EAST VIEW FAMILY CARE		STREET ADDRESS, CITY, STATE, ZIP CODE 3208 TEX'S FISHCAMP ROAD CONNELLY SPG, NC 28612		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 183	Continued From page 1	C 183		
C 183	Outside Premises-Clean, Safe SECTION .0300 - THE BUILDING 10A NCAC 13G .0318 OUTSIDE PREMISES (a) The outside grounds of new and existing family care homes shall be maintained in a clean and safe condition. This Rule is not met as evidenced by: 1. At the time of the survey it was observed that there was a build-up of algae on the brick surfaces of the exit landing and stairs on the right side of the facility. * For all deficiencies listed above provide documentation of completed work in the form of photographs, receipts, invoices, etc. All deficiencies listed above were discussed with on-site staff during the exit interview.	C 183		