

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL001148	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED R 05/23/2019
NAME OF PROVIDER OR SUPPLIER ALAMANCE HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 2766 GRAND OAKS BOULEVARD BURLINGTON, NC 27215		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 000}	Initial Comments Report of a Biennial Follow Up Construction Survey report by Frank Strickland on 0/23/2019: There are previous cited deficiencies from the Biennial Construction Survey that require corrective action and a new Plan of Correction is required.	{C 000}		
{C 111}	Must Have Current San. & Fire Safety Reports SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0302 DESIGN AND CONSTRUCTION(f) The facility shall have current sanitation and fire and building safety inspection reports which shall be maintained in the home and available for review. This Rule is not met as evidenced by: 1-Based on record review, and interview with Executive Director the facility failed to maintain in the facility, current (completed within the last twelve months) annual inspection report(s) required by this Rule. Findings on 05/23/2019: (a) The current Annual Fire Alarm System Inspection and Testing Report in accordance with NFPA 72, is not available for review by the Surveyor.	{C 111}		
{C 189}	Building Equipment Maintained Safe, Operating SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult	{C 189}		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL001148	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED R 05/23/2019
NAME OF PROVIDER OR SUPPLIER ALAMANCE HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 2766 GRAND OAKS BOULEVARD BURLINGTON, NC 27215		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 189}	Continued From page 1 care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 4-Based on Observation, fire rated doors of hazardous or Incidental areas are not being maintained in a safe and operating condition. This could affect residents, staff and visitors if smoke/fire is not contained in Room of origin. Findings on 05/23/2019: (b) Mech/Elec/Paint Room - the corridor door (45 min rated, self-closing), is falling apart and is not providing any fire protection. 8-Based on observation, the smoke tight corridor doors are not maintained in a safe and operating condition. Findings on 05/23/2019: (a) MCU Service Hall Clean Linen - the corridor door is falling apart. It hits the doorframe, taking extra force and effort to close and latch. (b) MCU Service Hall Custodian - the corridor door has a zero to 1/4 inch gap between the side of the door and the doorframe's stop on the hinge side.	{C 189}		
{C 199}	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of	{C 199}		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL001148	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED R 05/23/2019
NAME OF PROVIDER OR SUPPLIER ALAMANCE HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 2766 GRAND OAKS BOULEVARD BURLINGTON, NC 27215		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
{C 199}	Continued From page 2 two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1-Based on Observation and testing with a thin plastic sheet, the facility failed to maintain the ventilation system in proper working order. This could affect all residents, staff, and visitors by preventing the exhausting of odors. Findings on 05/23/2019: (a) Bedroom 107 Bathroom - the required exhaust ventilation system did not work, and there is odor. (b) AL Nurse Station Staff Restroom - the required exhaust ventilation system did not work, and there is odor. (c) Service Hall Custodian - the required exhaust ventilation system did not work, and there is odor. (d) MCU Nurse Station Staff Restroom - the required exhaust ventilation system did not work, and there is odor.	{C 199}		