



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Legacy House	Provider Number	2493
Address	803 S LANE ST ,	Approval Status	Approved
City, State, Zip	Seattle, WA	Facility Type	Residential Care

On 10/30/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative

Signature

JEANOT MUSTER DIRECTOR OF FACILITIES
Print Name and Title

Deputy State Fire Marshal Jason Van Gorkum
2502 112 ST E
Tacoma WA 984455104
(509) 406-7209

Jason Van Gorkum Date: 2025.10.30
16:16:39 -07'00'
Signature

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Legacy House	Provider Number	2493
Address	803 S LANE ST ,	Approval Status	Disapproved
City, State, Zip	Seattle, WA	Facility Type	Residential Care

On 09/18/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

1 NFPA 80 Fire /Smoke Dampers Inspection and Testing

19.4 Periodic Inspection and Testing. 19.4.1 Each damper shall be tested and inspected 1 year after installation. 19.4.1.1 The test and inspection frequency shall then be every 4 years, except in hospitals, where the frequency shall be every 6 years.	The following deficiencies were cited as a result of this inspection: At the time of inspection, the following paperwork was not provided: 1. Fire/smoke damper inspection will need to be performed and documented All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.
--	---

Next inspection scheduled on or after: 10/18/2025

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Deputy State Fire Marshal Jason Van Gorkum
2502 112 ST E
Tacoma WA 984455104
(509) 406-7209

Signature

Print Name and Title

Min Huang Senior Services Manager



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Legacy House
803 S LANE ST,
City, State, Zip Seattle, WA 98104

Provider Number 2493
Approval Status Disapproved
Facility Type Residential Care

On 05/21/2025 the Office of the State Fire Marshal conducted a re-inspection at your facility. Listed below are violations that have not been corrected.

Code Requirement	Statement of Violation
------------------	------------------------

1 NFPA 80 Fire /Smoke Dampers Inspection and Testing

19.4 Periodic Inspection and Testing.
19.4.1 Each damper shall be tested and inspected 1 year after installation.
19.4.1.1 The test and inspection frequency shall then be every 4 years, except in hospitals, where the frequency shall be every 6 years.

The following deficiencies were cited as a result of this inspection:

At the time of inspection, the following paperwork was not provided:

1. Fire/smoke damper inspection will need to be performed and documented

All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.

Next inspection scheduled on or after: 06/20/2025

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Signature

Deputy State Fire Marshal Jason Van Gorkum
2803 156 AVE SE
Bellevue WA 98007
(509) 406-7209

Signature



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Legacy House	Provider Number	2493
Address	803 S LANE ST ,	Approval Status	Disapproved
City, State, Zip	Seattle, WA 98104	Facility Type	Residential Care

On 02/11/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

1 Time

Drills shall be held at unexpected times and under varying conditions to simulate the unusual conditions that occur in case of fire.

Exceptions:

1. In severe climates, the fire code official shall have the authority to modify the emergency evacuation drill termination points and frequency.
2. In Groups I-1, I-2, I-3 and R-4, where staff-only emergency evacuation drills are conducted after visiting hours or where care recipients are expected to be asleep, a coded announcement shall be an acceptable alternative to audible alarms.

(IFC 405.5 2021)

The following deficiencies were cited as a result of this inspection:

At the time of inspection, the following paperwork was not provided:

1. Facility cannot provide documentation for the completion of twelve planned and unannounced fire drills in the previous 12 months.

The following drills are missing.
3rd Shift - Quarter 3 and 4

All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.

2 Testing

Horizontal and vertical sliding and rolling fire doors shall be inspected and tested annually to confirm proper operation and full closure. Records of inspections and testing shall be maintained.

(IFC 705.2.6 2018)

The following deficiencies were cited as a result of this inspection:

At the time of inspection, the following paperwork was not provided:

1. Facility will need to provide documentation of annual inspection of horizontal or vertical Fire Doors.

All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.



Washington State Patrol
Fire Protection Bureau

Phone: (360) 596-3900

Business Name Legacy House	Provider Number 2493
Address 803 S LANE ST ,	Approval Status Disapproved
City, State, Zip Seattle, WA 98104	Facility Type Residential Care

On 02/11/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

3 Testing and Maintenance

Sprinkler systems shall be tested and maintained in accordance with Section 901.

(IFC 903.5 2021)

The following deficiencies were cited as a result of this inspection:

At the time of inspection, the following paperwork was not provided:

1. Annual forward flow test (NFPA 25 13.7.2)

All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.

4 Inspection, Testing and Maintenance

The maintenance and testing schedules and procedures for fire alarm and fire detection systems shall be in accordance with Sections 907.8.1 through 907.8.5 and NFPA 72. Records of inspection, testing and maintenance shall be maintained.

(IFC 907.8 2021)

The following deficiencies were cited as a result of this inspection:

At the time of inspection, the following paperwork was not provided:

1. Annual report from 5/3/2024 shows deficiencies on report. 6 expired batteries.

All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.

5 Power Test

Battery-powered emergency lighting equipment shall be tested annually by operating the equipment on battery power for not less than 90 minutes.

(IFC 1031.10.2 2021)

The following deficiencies were cited as a result of this inspection:

At the time of inspection, the following paperwork was not provided:

1. Annual 90 minute power test had not been performed and documented

All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Legacy House	Provider Number	2493
Address	803 S LANE ST ,	Approval Status	Disapproved
City, State, Zip	Seattle, WA 98104	Facility Type	Residential Care

On 02/11/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

6 Chute Discharge Protection

Chute discharges shall be equipped with a self-closing or automatic-closing opening protective in accordance with Section 716 of the International Building Code and having a fire protection rating of not less than 1 hour.

(IFC 1103.4.9.5 2021)

At time of inspection the following was observed:

1. Chute found on the 4th floor would not latch.

7 Maintenance

Emergency and standby power systems shall be maintained in accordance with NFPA 110 and NFPA 111 such that the system is capable of supplying service within the time specified for the type and duration required.

(IFC 1203.4 2021)

The following deficiencies were cited as a result of this inspection:

At the time of inspection, the following paperwork was not provided:

1. Log of weekly inspections
2. Monthly 30-minute full load test ✓
3. Diesel fuel testing 4/23/24 ✓

All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.

8 NFPA 80 Fire /Smoke Dampers Inspection and Testing

19.4 Periodic Inspection and Testing.

19.4.1 Each damper shall be tested and inspected 1 year after installation.

19.4.1.1 The test and inspection frequency shall then be every 4 years, except in hospitals, where the frequency shall be every 6 years.

The following deficiencies were cited as a result of this inspection:

At the time of inspection, the following paperwork was not provided:

1. Fire/smoke damper inspection will need to be performed and documented

All inspection reports must verify that the system has no deficiencies, or document that all deficiencies have been corrected.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Legacy House	Provider Number	2493
Address	803 S LANE ST ,	Approval Status	Disapproved
City, State, Zip	Seattle, WA 98104	Facility Type	Residential Care

On 02/11/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

9 NFPA 80 Fire Door Inspection and Testing

5.2.1 Inspection and Testing. Upon completion of the installation, door, shutters, and window assemblies shall be inspected and tested in accordance with 5.2.4.

5.2.4 Periodic Inspection and Testing.

5.2.4.1 Periodic inspections and testing shall be performed not less than annually.

5.2.2.4 A record of all inspections and testing shall be provided that includes, but is not limited to, the following information:

1. Date of inspection
2. Name of facility
3. Address of facility
4. Name of person(s) performing inspections and testing
5. Company name and address of inspecting company
6. Signature of inspector of record
7. Individual record of each inspected and tested fire door assembly
8. Opening identifier and location of each inspected and tested fire door assembly
9. Type and description of each inspected and tested fire door assembly
10. Verification of visual inspection and functional operation
11. Listing of deficiencies in accordance with 5.2.3, Section 5.3, and Section 5.4

And the following shall be checked:

1. Labels are clearly visible and legible
2. No open holes or breaks exist in surfaces of wither the door or frame
3. Glazing, vision light frames, and glazing beads are intact and securely fastened in place, if so equipped.
4. The door, frame, hinges, hardware, and non combustible threshold are secured, aligned and in working order with no visible signs of damage
5. No parts are missing or broken
6. Door clearances do not exceed clearances listed in 4.8.4 and 6.3.1.7
7. The self-closing device is operational,; that is, the active door completely closes when operated from the full open position
8. If a coordinator is installed, the inactive lead close before the active lead

At time of inspection the following was observed:

1. Resident door 223 shows a gap on top of door. ✓

2/12/2025



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Legacy House	Provider Number	2493
Address	803 S LANE ST ,	Approval Status	Disapproved
City, State, Zip	Seattle, WA 98104	Facility Type	Residential Care

On 02/11/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
9. Latching hardware operates and secures the door when it is in the closed position 10. Auxiliary hardware items that interfere or prohibit operation are not installed on the door or frame 11. No field modification to the door assembly have been performed that void the label. 12. Meeting edge protection, gasketing and edge seals where required, are inspected to verify their presence and integrity 13. Signage affixed to a door meets the requirements listed in 4.1.4	

Next inspection scheduled on or after: 03/13/2025

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.


Owner or Authorized Representative


Signature

SALLY DING & FACILITIES SUPERVISOR
Print Name and Title

Deputy State Fire Marshal Jason Van Gorkum

2803 156 AVE SE
Bellevue WA 98007
(509) 406-7209


Signature