

STATEMENT OF DEFICIENCIES	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: AL11911216	(X3) DATE SURVEY COMPLETED 04/19/2019
NAME OF PROVIDER OR SUPPLIER BROOKDALE SARASOTA MIDTOWN	STREET ADDRESS, CITY, STATE, ZIP CODE 2186 BAHIA VISTA STREET SARASOTA, FL 34239	
SUMMARY STATEMENT OF DEFICIENCIES (FINDINGS PRECEDED BY TAGS AND REGULATORY IDENTIFYING INFORMATION)		
0000 - Initial Comments An unannounced emergency power plan monitoring survey was conducted through at Brookdale Sarasota Midtown, an assisted living facility in Sarasota, Florida. The following is a description of the deficiency: 0200 - Emergency Environmental Control - 58A-5.036 FAC Based on record review and staff interview, the facility failed to ensure compliance with the emergency environmental control plan for assisted living facilities. The findings included: On, record review revealed no evidence of implementation of the emergency power plan (EPP) by as required by regulation. In addition, there was no evidence of a request for an extension to implement the emergency power plan. On at approximately 2:45 p.m., the facility Executive Director said she would obtain a copy of an extension from corporate. On at 12:54 p.m., a second request for proof of an extension to implement the emergency power plan was made to the facility Executive Director. On the facility Executive Director provided a copy of a variance or extension of implementation of the EPP until On at 10:30 a.m., the facility Executive Director acknowledged there was no documented evidence of a current variance or extension from implementing the emergency power plan. Class III		