



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name The Arbor at Bremerton
Address 3510 9TH ST,
City, State, Zip Bremerton, WA 98312

Provider Number 2619
Approval Status Approved
Facility Type Residential Care

On 01/22/2024 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

1 Admin Complaint

COMPLAINT # 114775

Here's a complaint of sprinkler head burst

Please include the answers to the following questions in your report in FDM.

1. The cause of the fire?
2. If the sprinklers were activated?
3. If there was an evacuation / how many were evacuated?
4. If there were injuries / how many?
5. Did the fire department respond? Yes, No

COMPLAINT # 114775

On January 22, 2024 a complaint investigation was conducted at The Arbor at Bremerton located at 3510 9th Street, Bremerton, WA 98312.

An interview was conducted with the Administrator and Assistance Maintenance Director in regards to the sprinkler system going down due to burst pipes. The wet system is currently working, dry system for the front overhang is current down and facility is on fire watch. Dry system is scheduled to be fixed.

There were no signs of a fire, the sprinkler system was activated due to burst pipes, there were no evacuations, there were no injuries and fire department did respond.

Next inspection scheduled on or after:

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

NOT AVAILABLE
Signature

Print Name and Title

Deputy State Fire Marshal Raul Murcia
PO BOX 42642
Olympia WA 98504
(360) 819-0067

[Signature]
Signature